

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 07 Jul 2021

Preliminary Advice

Insured Vehicle No	: GBJ11S	Accident Date	: 26/06/2021
TP Vehicle No	: GX8385C	Assignment Date	: 01/07/2021
Make	: TOYOTA DYNA 150	Est. Duration of Repair	: 4
Date of Inspection	: 05/07/2021		
Inspection At	: BH AUTO SERVICES PTE LTD (SIN MING) BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C, #01/111/113/115/117 SINGAPORE 575636		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,921.90
Revised Amount	:S\$	2,334.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,334.68

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :