COMFORTDELGRO ENGINEERING PTE LID REPAIR ESTIMATE\* VEHICLE NO SH8670X 23/06/21 MAKE CHIANG/ NTUC MODEL HYU- 140 Type Amount Qty **Unit Price** Parts Description/ Labour \$1,106.00 REAR BUMPER COVER de / \$71.20 REAR BUMPER BRACKET SIDE LH/RH \$35.60 \$428.40 REAR BUMPER REINFORCEMENT 7. \$67.90 BOOTLID EMBLEM 1-40 \$52.40 1 BOOTLID EMBLEM CRDI \$63.10 X BOOTLID HEMBLEM - X11 \$22.00 \$2.20 10 REAR BUMPER CLIPS Ne \$64.00 X \$32.00 2 REAR BUMPER REFLECTOR LH/RH LSV \$228.00 REAR BUMPER UNDER COVER SUL 147630 \$2,103.00 SUB TOTAL \$420.60 20.00% \$1,682.40 **DISCOUNTED TOTAL** 1181.04 \$135.70 1 REAR REVERSE SENSOR X SU 10.00% \$30.00 1 BOOTLID TEL NUMBER STICKER N \$30.00 1|BOOTLID COMFORTDELGRO STICKER \* \$50.00 1 REAR BUMPER ADVERTISEMENT \* \$50.00 1 REAR BUMPER MAT SUL \$282.13 Labour Charge 280,5560.00 Panel Beating 5vs600.00 Spray Painting Charge 40 \$60.00 Remove/refix reverse sensor 1 × \$60.00 **Tuff Kote** MX \$60.00 Check Lighting & Wiring \$1,340.00 TOTAL LABOUR \$3,304.53 **ESTIMATE TOTAL** This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Liveh No:

Signature:

Date:

1181.04 PASUL
160.00 Hp 90010068

2161.04 3 days
20% Hs
1728.83 29/06/21@1600hs

45-1700 Rasy afternix