



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007231/Auf3e2 Date: 27/08/2021 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 350A	Veh. Inspected	YN 3696C	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/06/21/5046	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	01/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi FE83BE6SRDEA	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	FE83BEA21028	Colour	BLUE	
Odometer	241902 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16	OTANI	6 mm	
L/H Front Tyre	7.00 R16	OTANI	6 mm	
R/H Rear Tyre	7.00 R16	OTANI	6 mm	
L/H Rear Tyre	7.00 R16	OTANI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2021	Inspection Date	06/07/2021	
Survey held at	ISHARE AUTO PTE. LTD. 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	