

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 30/06/2021

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : CHONG CHEE SENG, KLENN
: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED
Certificate No : P10493990R00 Accident Date : 25/06/2021
Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Nett Item

1	FRONT BUMPER	✓ 682.90	de ✓
1	FRONT BUMPER LOWER GARNISH	✓ 195.20	mt ✓
10	FRONT BUMPER CLIPS	✓ 50.00	ner ✓
1	FRONT BUMPER REINFORCEMENT	✓ 831.50	? bt ✓
1	FRONT BUMPER BEAM	415.70	Kun ✓
1	FRONT BUMPER SPONGE	✓ 219.50	Pena ✓
2	FRONT BUMPER REINFORCEMENT BRACKET	✓ 387.40	bt ✓
2	FRONT BUMPER LOWER ABSORBER	219.00	Kun ✓
1	FRONT BUMPER RETAINER RH	✓ 25.40	ner ✓

Date : 30/06/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00

Accident Date : 25/06/2021

Vehicle No : SLV-5173-T

Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE	✓ 486.00	ang ✓
10	FRONT GRILLE CLIPS	✓ 80.00	ang ✓
1	FRONT GRILLE LOGO	✓ 125.40	ang ✓
1	HEADLAMP RH	✓ 3,243.00	ang ✓
1	BONNET	✓ 1,134.50	ang ✓
10	BONNET INSULATOR CLIPS	100.00	ang ✓
2	BONNET HINGE RH/LH	✓ 130.00	ang ✓
1	BONNET LOCK	70.00	ang ✓
1	FRONT FENDER RH	753.50	ang ✓
1	FRONT FENDER INNERSHIELD RH	✓ 128.30	ang ✓

Date : 30/06/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00

Accident Date : 25/06/2021

Vehicle No : SLV-5173-T

Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
10	FRONT FENDER SHIELD CLIPS	✓ 50.00	Per ✓
1	FRONT FENDER WHEELARC GARNISH RH	✓ 540.50	Pde ✓
1	FRONT BUMPER SDIE GARNISH RH	✓ 125.50	ent ✓
1	FRONT FOGLAMP RH	301.00	Run.
1	HEADLAMP TOP PANEL RH	83.90	Rp
1	SUPPORT TOP PANEL	588.10	Rp
1	SUPPORT LOWER PANEL	110.00	Rp
1	WIPER WASHER TANK	188.50	Run.
1	FRONT AIRGUIDE RH	✓ 90.20	Pde ✓

Date : 30/06/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00 , Accident Date : 25/06/2021

Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	11355.00	
	Discount 10% On Parts	(1135.50)	
	<u>Special Nett Item</u>		
1	FRONT NUMBER PLATE	35.00	btd ✓
1	COOLANT	30.00	Run. ✓
	Sub Total	65.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,000.00	600 ✓
	TO RESPRAY AFFECTED AREAS	1,000.00	700 ✓
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30 ✓

Date : 30/06/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : CHONG CHEE SENG, KLENN

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10493990R00 Accident Date : 25/06/2021

Vehicle No : SLV-5173-T Make & Model : NISSAN QASHQAI 1.2 DIG-T CVT 1197

Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO TOP UP AIRCON GAS	120.00	? 100 ✓ acc.
	Sub Total	2170.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12,454.50

Remarks:

SUB TOTAL

GST 7.0 % 871.82

TOTAL 13,326.32

Surveyor's name:

Tanphui 97495747

Principal's name: CHONG CHEE SENG, KLENN

Survey Date & Time:

5/7/2021 330 pm

Plp Repair before paint
tanphui@khantam.com
7 days