## 辉陽汽車有限公 HUI YANG MOTOR PTE. LTD. Contact Add: SIN MING AUTOCARE BIR 176 Sin Ming Drive #04-02 Singapore Tel: 64515752 (2 Lines). Fax: 64514658 GST Reg No. 201629438M

30/06/2021

Owner:

Renny Afre Pary

160	THIMS CAR I DACKED TO THE		
ESTIN	TATE TO DESCRIBE TO THE LEASING PTE LTD		2 days
lpe	TATE TO REPAIR HONDA SHUTTLE 1	R. R. A. P. S. C. S. Commission of the Commissio	H3236X By \$ 1,193.70 X
1pc	and sundate.	Accides)	№ 8 32.30 X
1pc	rear tailgate "H" logo	7	rec 8 55.00 L
Ipc	rear tailgate "SHUTTLE" emblem	4	1 5 78.90 K
lpc	rear tailgate "HYBRID" emblem		14 S 383.10 X
1pc	rear tailgate chrome rear tailgate LH refector		Gy \$ 340.80
2pcs	rear tailgate hinge @\$65.50		RS 131.00 X
10pcs	rear tailgate spolier cilp @\$5.00		ans 50.00 X
lset	rear tailgate windscreen moulding	(4)	nas 195.00 ×
	rear tailgate inner lock	(4)	72 \$ 189.40 X
1pc	rear tailgate inner rubber		168.50 X
lpc	rear tailgate inner garnish	(n) cm	mten s 320.00 20
lpc	rear LH taillamp		Gr 8 520.50
lpc	rear taillamp lower bracket @\$89.50		125 179.00 ×
2pcs		19)	Def? \$ 1,150,60 ×
Ipc	rear bumper		1 S 53.00 X
2pcs	rear bumper side retainer @\$26,50		Ph s 65.00 x
1pc	rear bumper LH refector		sh \$ 85.00 X
1pc	rear bumper LH refector garnish		hs 75.00 x
1pc	rear bumper LH refector inner sponge		RS 601.50 X
lpc	rear end panel		ms 90.50 7
pc	rear end panel outer sensor		mg cm 195.55 2
pc	rear end panel inner garnish		
TOTAL PROPERTY.	rear end panel LH side panel		
рс	rear floot panel garnish box		CM \$ 295.20 2
DC	Feat Hoot paner garnish/ 458		mging \$ 658.50 2
C	rear fender LH inner garnish/ 730  LKK Auto Consu	Itants hence not	ify \$ 7,492.55
	The state of the s	The second secon	A STATE OF THE PARTY OF THE PAR

less 20%

rear parking sensor

lp Ip

1set

set

the Repairer of the following:

Third party survey is on a "Without Prejudice" basis net.
 S.nett.

. No illegal modification(s) is allowed

sealant

wiring

tuffkote

spray painting

labour charges

Total

· To resurvey before/after spray painting To display damaged part(s) during resurvey · Parts prices are subject to confirmation

rear number plate & casing supplementary item(s) must be resurveyed and s.nett

Remove & refit rear windscreen grass Repairer

Date:

\$ 1,498.51 \$ 5,994.04

X 7 /81 Shorted 280.00 S/ 50.00 X

120.00 × S NN 80.00 X

100.00 201

100.00

1,000,00 1,000.00 200/

8,724.04

