

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Billy Tan

Date: 02 Jul 2021

**Preliminary Advice**

Vehicle No	: SJK3387M	Accident Date	: 25/06/2021
Make	: TOYOTA HIACE	Policy No.	: DMCVSNA00003052101
Assignment Date	: 01/07/2021	Excess	: S\$1,000.00
Date of Inspection	: 02/07/2021	Est. Duration of Repair	: 24
Inspection At	: AUTO SOON PTE LTD (HQ) BLOCK 176 SIN MING DRIVE, #01-10 SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,484.52
Revised Amount	:S\$	17,202.04
Check Items (Estimated)	:S\$	17,929.94
Total	:S\$	35,131.98
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	0.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,000.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :