

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909
 Attention : Motor Claim Department
 Contact : +65 6389 6111 Fax No. : +65 6222 1033

NOT Authorized
L1 Sing @ 30, 800h
Resurvey After claim
Ex @ 1000h

Estimate : ES000534

Date : 29/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSNA00003052101

S/N	Quantity	Particular	24 days	Unit Price	Amount S\$
LIST ITEMS :					
1.	1	Windscreen assy		969.30	—
2.	1	Windscreen moulding		78.45	—
3.	1	Windscreen lower garnish		298.30	—
4.	1	Windscreen lower garnish weatherstrip		110.30	—
5.	2	Windscreen wiper arm assy	137.38	274.76	X
6.	1	Windscreen wiper blade		78.13	—
7.	1	Windscreen wiper linkages		390.30	—
8.	1	Windscreen washer tank assy		75.91	—
9.	2	Windscreen washer motor	168.31	336.62	X
10.	1	Bonnet assy		666.35	—
11.	1	Bonnet emblem		57.99	—
12.	1	Bonnet lock assy		96.97	—
13.	1	Bonnet lock panel		243.30	—
14.	1	Bonnet lock brace panel		77.09	X
15.	2	Bonnet weatherstrip no:1	MSGA 95.00	190.00	X
16.	2	Bonnet hinges	64.58	129.16	—
17.	1	N/s bonnet hinges support panel		101.00	—
18.	1	Radiator grille assy		433.81	—
19.	1	Radiator grille apron panel		331.20	X
20.	1	Bumper facial		529.37	—
21.	10	Bumper facial clips	5.00	50.00	—
22.	1	Bumper lower air grille assy		213.30	X
23.	1	Bumper top beam		165.75	X
24.	1	Bumper reinforcement		296.35	X
25.	1	N/s bumper fog lamp cover		28.59	—
26.	1	N/s bumper retainer		185.02	—

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

Estimate : ES000534

Date : 29/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSN00003052101

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909
 Attention : Motor Claim Department
 Contact : +65 6389 6111 Fax No. : +65 6222 1033

S/N	Quantity	Particular	Unit Price	Amount S\$	
27.	2	Head lamp assy	546.90	1,093.80	✓
28.	1	Head lamp support panel		R _L 358.34	✓
29.	1	Turbo charger air inlet cowlng		R _R 296.68	X
30.	1	Bulk head top panel		R _L 1,189.30	✓
31.	1	Bulk head lower panel		R 1,893.20	✓
32.	1	Bulk head lower panel insulator		S _W 331.30	✓
33.	1	N/s corner view mirror assy		CMA 209.35	✓
34.	1	N/s corner panel assy		R _L 168.75	✓
35.	1	N/s corner panel inner support		R _L 89.00	✓
36.	1	N/s A pillar outer assy		R _L 381.73	✓
37.	1	N/s A pillar inner panel		R _L 313.58	✓
38.	1	N/s A Pillar cover trim		D ₁₁ 146.31	✓
39.	1	N/s A pillar lower panel		R _L 190.67	✓
40.	1	N/s A pillar lower inner panel		R _L 117.44	✓
41.	1	N/s fender assy		R _L 231.30	✓
42.	1	N/s fender inner panel		R _L 556.30	✓
43.	1	N/s step garnish		CMA 165.16	✓
44.	1	N/s step panel assy		R _L 68.98	✓
45.	1	N/s step board panel		R _L 213.30	✓
46.	1	N/s step board inner panel		R _L 181.30	✓
47.	1	N/s door assy		R _L 1,606.07	✓
48.	1	N/s door outer moulding		R _L 134.51	✓
49.	1	N/s door top hinges		R _L 105.47	✓
50.	1	N/s door lower hinges		R _L 102.74	✓
51.	1	N/s door window glass		R _L 391.40	✓
52.	1	N/s door window channel		D ₁₇ 215.07	✓
53.	1	N/s door window regulator and motor		R _L 918.37	✓
54.	1	N/s door inner lock assy		T _L 509.23	✓

CONTINUE / ...

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909

Attention : Motor Claim Department

Contact : +65 6389 6111 Fax No. : +65 6222 1033

Estimate : ES000534

Date : 29/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSNA00003052101

S/N	Quantity	Particular	Unit Price	Amount S\$
55.	1	N/s door inner lock catch	46.14	✓
56.	1	N/s door inner trim board	787.10	✓
57.	1	N/s door weatherstrip	295.12	508/1a
58.	1	N/s B pillar outer panel	396.79	✓
59.	1	N/s B pillar inner panel	576.30	X
60.	1	Instrument panel assy	756.30	✓
61.	1	Instrument support reinforcement assy	563.91	✓
62.	1	Instrumental panel centre garnish	427.24	✓
63.	1	Instrument centre console control panel	266.31	X
64.	1	Instrument centre console control switch	218.99	X
65.	1	Instrumental glove box	231.38	✓
66.	1	Air con evaporator blower and housing assy	1,015.17	✓
67.	1	Air con evaporator coil and housing	2,446.86	✓
68.	1	Air con air outlet centre grille	189.31	X
69.	1	Air con air side outlet grille	91.48	X
70.	1	Pax seat assy	785.30	X
71.	1	Engine room main cover panel	651.30	X
72.	1	Engine room main cover insulator	211.30	X
73.	1	Floor board panel assy	1,898.30	✓
74.	1	Floor board panel covering trim	661.30	✓
75.	1	N/s wire harness assy	551.30	✓
76.	1	N/s wire harness junction box	431.30	✓
77.	1	N/s fuse box junction	688.30	✓
78.	1	N/s fuse box wire harness	315.30	✓
79.	1	N/s wheel hud cap	152.23	X
80.	1	N/s wheel assy	385.31	X
81.	1	N/s wheel hud assy	326.30	✓
82.	1	N/s wheel hud bearing	283.25	✓

CONTINUE / ...

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909
 Attention : Motor Claim Department
 Contact : +65 6389 6111 Fax No. : +65 6222 1033

Estimate : ES000534

Date : 29/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVNA00003052101

S/N	Quantity	Particular	Unit Price	Amount S\$	
					<i>Dit</i> 752.39 ✓
83.	1	N/s wheel top control arm			<i>R</i> 464.23 ✓
84.	1	N/s wheel kunckle arm			<i>Dit</i> 390.41 ✗ SVC
85.	1	N/s wheel lower arm			<i>R</i> 154.30 ✗
86.	1	N/s wheel shock absorber			<i>R</i> 92.75 ✗
87.	1	N/s steering tie rod arm			<i>R</i> 3,405.30 ✗
88.	1	Steering rack assy			<i>R</i> 3,284.82 ✗
89.	1	Crossmember assy			
		List TotalS\$:		42,779.36	
		25.00% Discount S\$:		10,694.84	
				32,084.52	
		LABOUR :			
	1	To tow ambulance on dolly wheels, receipt enclosed	100.00	100.00	✓
	1	To replace windscreen assy	150.00	150.00	12cl
	1	To supply windscreen sealant and dam rubber	180.00	180.00	6clm
	1	To remove air con condenser to panel beat support panel	250.00	250.00	15cl
	1	To remove interior air con evaporator, heat exchanger	350.00	350.00	25cl
	1	To remove interior pax seats to facilitate repair	280.00	280.00	12cl
	1	include floor carpet, all trims covering and roof top upholstery in repairs.	250.00	250.00	12cl
	1	To refocus head lamp, remove damaged section wire harness, junction box , instrumental wire harness and engine loom in repair	380.00	380.00	20cl

CONTINUE / ...

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909

Attention : Motor Claim Department

Contact : +65 6389 6111 Fax No. : +65 6222 1033

Estimate : ES000534

Date : 29/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSNA00003052101

S/N	Quantity	Particular	Unit Price	Amount S\$
		to facilitate replacement		
1		To putty and respray complete damaged portion	1,380.00	1,380.00
1		To computer check/readjust wheel realignment in repair.	100.00	100.00
1		To remove/cut damaged section and restraighthen/ recondtion chassis frame and replace bulk head panels, floor board, fender innner panel. To panel beat all damaged panels, weld/fix panels include relaign bumper and panels in repair	1,980.00	1,980.00
Labour Total S\$:				5,400.00

1300

60

1800

Total S\$: 37,484.52


 AutoSoon Pte Ltd

Kindly note above mentioned parts are visible quoted, we reserve our right to submit further quote if further parts are found damaged while undergoing repair.

Date Survey: _____ Surveyor Name: _____ Co Name: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	794E
Vehicle Details	
Vehicle No.:	SJK3387M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Jul 2021
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0DX A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1KD1796274
Chassis No.:	KDH2210002692
Maximum Power Output:	-
Open Market Value:	\$40,542.00
Original Registration Date:	15 Oct 2008
First Registration Date:	15 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 02 Jul 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIAs Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/06/2021 17:17 (SGT)
Date of Accident	25/06/2021 08:18 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TIONG BAHRU ROAD JUNCTION OF LOWER DELTA ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK3387M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	AMBULANCE MEDICAL SERVICES PTE LTD
Company Reg No	2XXXXX794E
Email Address	AUTOSOONL@GMAIL.COM
Mobile Phone No	(Phone) +65-87494180
Alternative Phone No	+65-87494180

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2754

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	DMCVSNA00003052101
Cover Note Number	DMCVSNA00003052101

DRIVER

Name of Driver	MUHAMMED MEERAN ALI KHAN BIN RAYEES AHMAD KHAN
NRIC No	SXXXX632H

Date Of Birth	19/10/1983
Occupation	Outdoor
Date Of Driving Pass	28/02/2020
Driving experience	1 YEAR AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-87494180
Alt. Phone Number	-
Email Address	AUTOSOONL@GMAIL.COM
Address	APT BLK 992A BUANGKOK LINK
Address complement	#12-173
Postcode	531992
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO.: T/20210625/7015

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	TREE BARK
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time 25 JUN 2021 Sketch Plan	 Driver's Signature (if driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel
--	---	--





**SINGAPORE
POLICE FORCE**



T/20210625/7015

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20210625/7015

CONTINUATION OF REPORT

Driver			
Name	MUHAMMED MEERAN ALI KHAN BIN RAYEES AHMAD KHAN	ID No.	S8332632H
Related Vehicle	SJK3387M (Van)	Contact No.	87494180
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

I driving about approximately 50 km along Tiong Bahru Road towards the traffic control light junction of Lower delta Road, As the traffic control light was green and in my favor I proceed to turn into Lower Delta Road toward Granges Road. As I steer my ambulance in to Lower Delta Road suddenly I felt my ambulance aqua plane because the was a puddle of rain water on the road.

Hence, I lost control and it skidded towards the center divider of the road along Lower Delta and it collided on to a tree, causing only the tree bark sustained some minor damaged.

Nobody or others was involved in this accident.

AutoSoon Pte Ltd

Registration No: 200709808N

Block 176 Sin Ming Drive #01-10 Sin Ming Autocare Singapore 575721 Tel: 64526657 Fax : 64514618

Service With A Smile

7th July 2021

Land Transport Authority
10, Sin Ming Drive
Singapore 575701

Attn: Officer in Charge,
Vehicle Engineering Dept.

Dear Sir,

Re: Ambulance vehicle Regn no: SJK3387M, model: Toyota Hiace DX 3.0 A with Chassis no:
KDH221-0002692

We, above mentioned workshop has been entrusted with this damaged vehicle repairs by our client's M/s Ambulance Medical Services Pte Ltd, the said vehicle was involved in an accident on 25-06-2021, attached GIA and T/police accident reports for your kind perusal.

We seek your kind cooperation and permission to allow us to replace the vehicle front damaged cowl panels, where the vehicle chassis identification number was stamped by Toyota factory.

The new cowl panel part number 55700-26470 is available for replacement for the said vehicle, attached part purchased invoice and EPC showing the replacement panel for your kind attention

The replacement of the cowl panel will not affect the integrity of the chassis and road worthiness of the vehicle.

Kindly be assure we will carry out sound engineering practices for panels installation and welding to this vehicle with utmost safety in mind for the passenger and driver in this repair.

Look forward to your kind and favorable reply to allow us to proceed with the said cowl panel replacement.

Please feel free to contact me anytime on my mobile no: 96351683 for any clarification you may require for the above mentioned matter.

Yours faithfully



Soon

cc: Ambulance Medical Services Pte Ltd
: China Taiping Insurance (S) Pte Ltd.

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909

Attention : Motor Claim Department

Contact : +65 6389 6111 Fax No. : +65 6222 1033

Supplementary Estimate : ES000535

Date : 25/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSNA00003052101

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	Radiator secondary assy	<i>RM</i> 952.32	✓
2.	1	Radiator secondary top hose	<i>PU</i> 42.03	✓
3.	1	Radiator secondary lower hose	<i>L</i> 56.38	X
4.	1	Radiator primary assy	<i>RT</i> 1,905.08	—
5.	1	Radiator cowling assy	<i>CM</i> 311.94	—
6.	1	Air con condenser	<i>RM</i> 1,521.10	—
7.	1	Air filter intake ducting	<i>RM</i> 166.32	—
8.	1	Air filter housing assy	<i>CM</i> 793.71	—
9.	1	Engine under cover	<i>CM</i> 637.20	—
10.	1	Engine main wire harness	<i>Tn</i> 3,189.30	—
11.	1	ABS brake actuator assy	<i>RM / Rd</i> 4,700.11	—
12.	2	ABS brake actuator piping assy	315.30 <i>Rd</i> 630.60	—
13.	6	ABS complete fluid piping	115.30 <i>Rd</i> 691.80	—
14.	1	ABS module wire harness	<i>CM</i> 1,863.30	—
15.	1	N/s fender moulding	<i>RM</i> 163.00	—
16.	1	N/s door control wire harness assy	<i>Tn</i> 368.00	—
17.	1	N/s roof_components wire harness	<i>Tn</i> 996.30	—
18.	1	N/s main fused box assy	<i>CM</i> 489.30	—
19.	1	N/s fuse box junction	<i>CM</i> 413.30	—
List TotalS\$:			19,891.09	
25.00% Discount S\$:			4,972.77	
			14,918.32	

1	LABOUR :	To prepare documents and letter of no objection to LTA	1,500.00	1,500.00	<i>Boh</i>
---	----------	--	----------	----------	------------

CONTINUE / ...

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909
 Attention : Motor Claim Department
 Contact : +65 6389 6111 Fax No. : +65 6222 1033


Supplementary Estimate : ES000535

Date : 25/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSNA00003052101

S/N	Quantity	Particular	Unit Price	Amount S\$
	1	engineering section for Bulks head, fire wall panels replacement include chassis frame number stamp and Vitas inspection services Additional unforeseen damaged repairs/panel beat and restraighten/recondition mid section chassis and body panel, interior floor board panel include realignment	1,200.00	1,200.00
		Labour Total S\$:		2,700.00

X

Total S\$: 17,618.32
 =====



AutoSoon Pte Ltd

Kindly note above mentioned parts are visible quoted, we reserve our right to submit further quote if further parts are found damaged while undergoing repair.

Date Survey: Surveyor Name: Co Name: