

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909

Attention : Motor Claim Department

Contact : +65 6389 6111 Fax No. : +65 6222 1033

Supplementary Estimate : ES000535

Date : 25/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSN00003052101

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Radiator secondary assy		952.32 ✓
2.	1	Radiator secondary top hose		42.03 ✓
3.	1	Radiator secondary lower hose		56.38 ✓
4.	1	Radiator primary assy		1,905.08 ✓
5.	1	Radiator cowlng assy		311.94 ✓
6.	1	Air con condenser		1,521.10 ✓
7.	1	Air filter intake ducting		166.32 ✓
8.	1	Air filter housing assy		793.71 ✓
9.	1	Engine under cover		637.20 ✓
10.	1	Engine main wire harness		3,189.30 ✓
11.	1	ABS brake actuator assy		4,700.11 ✓
12.	2	ABS brake actuator piping assy	315.30	630.60 ✓
13.	6	ABS complete fluid piping	115.30	691.80 ✓
14.	1	ABS module wire harness		1,863.30 ✓
15.	1	N/s fender moulding		163.00 ✓
16.	1	N/s door control wire harness assy		368.00 ✓
17.	1	N/s roof_components wire harness		996.30 ✓
18.	1	N/s main fused box assy		489.30 ✓
19.	1	N/s fuse box junction		413.30 ✓
List TotalS\$:				19,891.09
25.00% Discount S\$:				4,972.77
				14,918.32
LABOUR :				
1		To prepare documents and letter of no objection to LTA	1,500.00	1,500.00 ?

CONTINUE / ...

toSoon Pte Ltd

in Ming Drive #01-10
 ing AutoCare Singapore 575721
 : +65 64526657 Fax No. : +65 64514618
 l : autosoon1@gmail.com
 eg. No. : 200709808N Buss. Reg. No. : 20709808N

A TAIPIING INSURANCE (S) PTE LTD
 on Rd, #16-00
 leaf Tower
 pore 079909
 ion : Motor Claim Department
 ct : +65 6389 6111 Fax No. : +65 6222 1033

Supplementary Estimate : ES000535

Date : 25/06/2021
 Vehicle Num. : SJK 3387 K
 Make/Model : Toyota Hiace
 Chassis/Eng# : KDH221-0002692
 Accident Date : 25/06/2021
 Claim No. :
 Reference : OD/01/06/21
 Policy No. : DMCVSNA00003052101

Quantity	Particular	Unit Price	Amount S\$
1	engineering section for Bulks head, fire wall panels replacement include chassis frame number stamp and Vitas inspection services Additional unforeseen damaged repairs/panel beat and restraighten/recondition mid section chassis and body panel, interior floor board panel include realignment	1,200.00	1,200.00 ?
	Labour Total S\$:		2,700.00

Total S\$: 17,618.32



oSoon Pte Ltd

ny note above mentioned parts are visible quoted, we reserve our right to
 it further quote if further parts are found damaged while undergoing repair.
 Survey: Surveyor Name: Co Name:

AutoSoon Pte Ltd

Registration No: 200709808N

Block 176 Sin Ming Drive #01-10 Sin Ming Autocare Singapore 575721 Tel: 64526657 Fax: 64514618

Service With A Smile

7th July 2021

Land Transport Authority
10, Sin Ming Drive
Singapore 575701

Attn: Officer in Charge,
Vehicle Engineering Dept.

Dear Sir,

Re: Ambulance vehicle Regn no: SJK3387M, model: Toyota Hiace DX 3.0 A with Chassis no:
KDH221-0002692

We, above mentioned workshop has been entrusted with this damaged vehicle repairs by our client's M/s Ambulance Medical Services Pte Ltd, the said vehicle was involved in an accident on 25-06-2021, attached GIA and T/police accident reports for your kind perusal.

We seek your kind cooperation and permission to allow us to replace the vehicle front damaged cowl panels, where the vehicle chassis identification number was stamped by Toyota factory.

The new cowl panel part number 55700-26470 is available for replacement for the said vehicle, attached part purchased invoice and EPC showing the replacement panel for your kind attention

The replacement of the cowl panel will not affect the integrity of the chassis and road worthiness of the vehicle.

Kindly be assure we will carry out sound engineering practices for panels installation and welding to this vehicle with utmost safety in mind for the passenger and driver in this repair.

Look forward to your kind and favorable reply to allow us to proceed with the said cowl panel replacement.

Please feel free to contact me anytime on my mobile no: 96351683 for any clarification you may require for the above mentioned matter.

Yours faithfully



Soon

cc: Ambulance Medical Services Pte Ltd
: China Taiping Insurance (S) Pte Ltd.