

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21007247/KBS3Q2
Date: 27/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMP3708J	Insured Vehicle No :	SLR1576L
Date of Loss:	29/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002802

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP3708J		
Make & Model:	RENAULT SCENIC, 2.0 (A)	Engine No:	K9KF649D059994
Reg. Date:	24/09/2019 (Man. Year: 2019)	Chassis No:	VF1RFA00362894938
Colour:	Metallic Black	Odometer:	43870 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,861.19	1,492.89	8,368.30	84.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	900.00	2,080.00	69.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,841.19	2,392.89	10,448.30	81.37
Approved Total (Overridden) (S\$)		1,900.00		

(S\$)	12,841.19	1,900.00	10,941.19	85.20
+ GST 7.00/7.00% (S\$)	898.88	133.00	765.88	85.20
Nett Amount (S\$)	13,740.07	2,033.00	11,707.07	85.20
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 01/07/2021

Date Inspected: 05/07/2021

Estimated Period of Repair: 3.0 days

Inspected At: Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #06-43
Singapore 737869

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2021)
Parts:	143	RENAULT SCENIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP3708J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE OUTER PANEL	Repair	949.28 FL	*- FL
2	1		*TAILGATE PANEL STRIP	Serviceable	413.40 FL	*- FL
3	1		*EMBLEM DIAMOND	Necessary	189.40 FL	*138.10 FL
4	1		*EMBLEM RENAULT	Necessary	129.60 FL	*119.60 FL
5	1		*EMBLEM SCENIC	Necessary	151.44 FL	*151.44 FL
6	6		*RIVET	Not Necessary	55.44 FL	*- FL
7	1		*TRUNK DOOR LOCK	Repair	121.56 FL	*- FL
8	1		*STRIKER TRUNK DOOR	Repair	96.72 FL	*- FL
9	1		*REAR BUMPER	Cracked	1,152.96 FL	*1,152.96 FL
10	1		*REAR LOWER BUMPER	Serviceable	492.78 FL	*- FL
11	1		*REAR LOWER BUMPER SLIVER MOULDING	Serviceable	696.24 FL	*- FL
12	4		*REVERSE SENSOR	Serviceable	1,021.44 FL	*- FL
13	1		*REVERSE SENSOR HARDNESS	Serviceable	224.40 FL	*- FL
14	1		*REAR BUMPER RETAINER RH	Serviceable	288.96 FL	*- FL
15	1		*REAR BUMPER RETAINER LH	Serviceable	288.96 FL	*- FL
16	1		*REAR BUMPER BRACKET CENTRE	Repair	357.84 FL	*- FL
17	15		*RIVET ALUMINIUM	Not Necessary	105.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Repair	685.68 FL	*- FL
19	1		*REAR BUMPER PAD SUPPORT BRACKET	Serviceable	87.36 FL	*- FL
20	1		*REAR FLOOR PANEL	Repair	1,282.44 FL	*- FL
21	1		*REAR END PANEL OUTER	Repair	933.12 FL	*- FL
22	1		*REAR END PANEL INNER	Repair	421.92 FL	*- FL
23	1		*SEAL TRUNK DOOR	Serviceable	197.40 FL	*- FL
24	1		*EXHAUST HEAT SHIELD	Serviceable	259.20 FL	*- FL
25	1		*REAR WIPER BLADE	Serviceable	42.25 FL	*- FL
26	1		*BLADE HOLDER TRUNK	Serviceable	160.92 FL	*- FL
27	1		*NO PLATE LAMPS	Serviceable	37.83 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	6		*REAR BUMPER CLIPS	Necessary	42.00 FS	*42.00 FS
29	1		*REAR NO PLATE WITH CASING	Dented	60.00 FS	*45.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					10,945.54	1,649.10
- List Item Discount on L Items 10.00/10.00% (\$)					1,084.35	156.21
Total Parts (\$)					9,861.19	1,492.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEATING ,REALIGN REAR END PANEL ,TAILGATE ,REAR BUMPER AND ALL NECESSARY ETC	New	1,300.00	400.00
2	TO REMOVE AND REFIX REAR REVERSE SENSOR	New	300.00	60.00
3	TO APPLY ANTI RUST	New	180.00	0.00
4	TO PUTTY & SPRAY PAINTING TAILGATE ,REAR BUMPER ,END PANEL AND ALL NECESSARY ETC	New	1,200.00	440.00
Gross Labour Cost (\$\$)			2,980.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >