

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMP3708J
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00362894938

Estimation No. : E21050014
Date : 01/07/2021

No.	Code	Description	Qty	U/P	Amt
Section: Remark					
1		INDIA INT'L INS PTE LTD DOA: 29/06/2021 THIRD PARTY CLAIM	1.00	0.00	0.00
					Amt S\$ 0.00
					Discount (0.00%) S\$ 0.00
					Subtotal S\$ 0.00

Section: Parts

2	901523953R	TAILGATE OUTER PANEL	1.00	949.28	949.28	X
3	848108783R	TAILGATE PANEL STRIP	1.00	413.40	413.40	X
4	908895927R	EMBLEM "DIAMOND"	1.00	189.40	189.40	X
5	908924456R	EMBLEM "RENAULT"	1.00	129.60	129.60	X
6	908923255R	EMBLEM "SCENIC"	1.00	151.44	151.44	X
7	908B86823R	RIVET	6.00	9.24	55.44	X
8	905031335R	TRUNK DOOR LOCK	1.00	121.56	121.56	X
9	905700851R	STRIKER TRUNK DOOR	1.00	96.72	96.72	X
10	850226425R	REAR BUMPER	1.00	1,152.96	1,152.96	X
11	850189314R	REAR LOWER BUMPER	1.00	492.78	492.78	X
12	850703057R	REAR LOWER BUMPER SLIVER MOULDING.	1.00	696.24	696.24	X
13	253A44101R	REVERSE SENSOR	4.00	255.36	1,021.44	X
14	240154998R	REVERSE SENSOR HARDNESS	1.00	224.40	224.40	X
15	850448822R	REAR BUMPER RETAINER RH	1.00	288.96	288.96	X
16	850457145R	REAR BUMPER RETAINER LH	1.00	288.96	288.96	X
17	850429618R	REAR BUMPER BRACKET CENTRE	1.00	357.84	357.84	X
18	7703072047	RIVET ALUMINIUM	15.00	7.00	105.00	X
19	756100714R	REAR BUMPER REINFORCEMENT	1.00	685.68	685.68	?
20	850476580R	REAR BUMPER PAD SUPPORT BRACKET	1.00	87.36	87.36	?

Continue on next page...

Locare Pte Ltd

Unit #02-02/03 Carros Centre Singapore 737869
Tel: +65 6265 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMP3708J
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00362894938

Estimation No. : E21050014
Date : 01/07/2021

No.	Code	Description	Qty	U/P	Amt
21		745148151R REAR FLOOR PANEL	1.00	1,282.44	1,282.44 X
22		791004963R REAR END PANEL OUTER	1.00	933.12	933.12 X
23		791026675R REAR END PANEL INNER	1.00	421.92	421.92 X
24		908309596R SEAL TRUNK DOOR	1.00	197.40	197.40 X
25		205429585R EXHAUST HEAT SHIELD	1.00	259.20	259.20 X
26		287901560R REAR WIPER BLADE	1.00	42.25	42.25 X
27		287815094R BLADE HOLDER TRUNK	1.00	160.92	160.92 X
28		R265109646R NO PLATE LAMPS	1.00	37.83	37.83 X

Amt S\$ 10,843.54

Discount (10.00%) S\$ 1,084.35

Subtotal S\$ 9,759.19

Section: Special nett

29		REAR BUMPER CLIPS	6.00	7.00	42.00 ✓
30		REAR NO PLATE WITH CASING	1.00	60.00	60.00 45.00

Amt S\$ 102.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 102.00

Section: Labour

31		TO PANEL BEATING, REALIGN REAR END PANEL, TAILGATE, REAR BUMPER AND ALL NECESSARY ETC.	1.00	1,300.00	1,300.00 400
32		TO REMOVE AND REFIX REAR REVERSE SENSOR	1.00	300.00	300.00 60
33		TO APPLY ANTI RUST.	1.00	180.00	180.00 X
34		TO PUTTY & SPRAY PAINTING TAILGATE, REAR BUMPER, END PANEL AND ALL NECESSARY ETC.	1.00	1,200.00	1,200.00 400

Amt S\$ 2,980.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 2,980.00

Remarks:

INDIA INT'L INS PTE LTD
DOA: 29/06/2021
THIRD PARTY CLAIMS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remark Subtotal S\$ 0.00

Parts Subtotal S\$ 9,759.19

Special nett Subtotal S\$ 102.00

Labour Subtotal S\$ 2,980.00

Total S\$ 12,841.19