

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Kasyful Adzim Bin Mohamad Foaad
C/o: GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Invoice No. : CL/210335

Ref No. : GPM/04/2103/TP

Date : 17 June 2021

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>FBE 6396 T</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	S\$ 647.00

E & O. E

All cheque payment should be "Crossed" and made payable to " **C L APPRAISER PTE LTD** "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Kasyful Adzim Bin Mohamad Foaad
C/o: GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Date : 17 June 2021
Our ref : GPM/04/2103/TP

Accident Date : 10 April 2021
Inspection Date : 15 April 2021
Repairer Name : GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FBE 6396 T
Make / Model : Yamaha RXZ
Chassis No : PMY5PV100A0032113
Engine No : 5PV032113

Year / Capacity : 2010 / 133 cc
Colour : Red
Mileage : 37925

CONDITION OF TYRES

	Make	Size	Thrcad Balance	Rim
Front	Dunlop	2.50 -18	5 mm	Normal
Rear	Dunlop	2.50 -18	5 mm	Normal

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear and n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 102 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$7,500.00** on a contractual basis.

Under normal circumstances, the repair period would be about 20 (Twenty) working days.

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	N/s fork tube assy	Damage	\$ 680.00	\$ 680.00
1	Fairing cover (1 set)	Damage	\$ 1,550.00	\$ 1,550.00
1	N/s handle bar	Damage	\$ 115.00	\$ 115.00
1	Hand grip (1 set)	Damage	\$ 65.00	\$ 65.00
1	N/s handle bar end	Damage	\$ 32.00	\$ 32.00
1	Clutch lever	Damage	\$ 38.00	\$ 38.00
1	Meter assy	Intact	\$ 750.00	
1	Fuel tank	Damage	\$ 950.00	\$ 950.00
1	Front n/s footrest	Damage	\$ 85.00	\$ 85.00
1	Front n/s footrest bracket	Damage	\$ 115.00	\$ 115.00
2	Rear absorbers	Damage	\$ 570.00	\$ 570.00
1	Gear panel	Damage	\$ 55.00	\$ 55.00
1	Rear n/s footrest	Damage	\$ 28.00	\$ 28.00
1	Exhaust pipe assy	Damage	\$ 1,350.00	\$ 1,350.00
1	Exhaust protector	Damage	\$ 65.00	\$ 65.00
1	Rim assy (1 set)	Damage	\$ 1,500.00	\$ 1,500.00
1	Rear rim hub	Damage	\$ 220.00	\$ 220.00
1	Swing arm	Damage	\$ 850.00	\$ 850.00
1	Swing arm shaft	Necessary	\$ 55.00	\$ 55.00
1	Rear mudguard	Damage	\$ 95.00	\$ 95.00
1	Rear passenger handle	Damage	\$ 78.00	\$ 78.00
1	Rear taillamp	Damage	\$ 110.00	\$ 110.00
1	Rear fender	Damage	\$ 115.00	\$ 115.00
1	Seat	Damage	\$ 285.00	\$ 285.00
			\$ 9,756.00	\$ 9,006.00
			<i>Less 10%</i>	<i>\$ 975.60</i>
Total Cost - List Items			\$ 8,780.40	\$ 8,105.40

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
List Items Total c/f			\$ 8,780.40	\$ 8,105.40

SPECIAL NETT ITEMS

1	Number plate (1 set)	Damage	\$ 28.00	\$ 28.00
1	Fork oil	Necessary	\$ 15.00	\$ 15.00
1	Fork oil seal	Necessary	\$ 28.00	\$ 28.00
1	Steering cone (1 set)	Necessary	\$ 75.00	\$ 75.00
1	Swing arm bush	Necessary	\$ 75.00	\$ 75.00
1	Sticker (1 set)	Necessary	\$ 95.00	\$ 95.00
1	Rear tyre (Depreciation)	Damage	\$ 300.00	\$ 150.00
Total Cost - Special Nett items			\$ 616.00	\$ 466.00

Total cost of parts

\$ 9,396.40	\$ 8,571.40
-------------	-------------

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 9,396.40	\$ 8,571.40

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00
4	To check , repair and straighten body frame to the original position.	\$ 350.00	\$ 350.00

GRAND TOTAL

\$ 10,356.40	\$ 9,421.40
---------------------	--------------------

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,500.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K.H
Automotive Appraiser

