

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S1M037QY Date: 06th Aug 2021

Our Ref: CS3/ASM21005038/Gqce2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Yu Dominic Yishan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBE 6396T INSURED VEHICLE: SHD 7116M ACCIDENT DATE: 10/04/2021

We thank you for your instruction on 02/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBE 6396T from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles FBE 6396T and SHD 7116M.
- c) Police Report of Vehicles FBE 6396T.
- d) Final Repair Bill of FBE 6396T from M/s GP Service Pte Ltd.
- e) Colour damaged vehicle photographs of FBE 6396T.

Pre-Repair Inspection Date: 22/04/2021 at M/s GP Motoring Pte Ltd, 282 Macpherson Road, Singapore 348607.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBE 6396T Make & Model : Yamaha RXZ

Year of Registration : 2010

Chassis Number : PMY5PV100A0032113

Engine Capacity : 133 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.