

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9755R**AAD2106-100***Not Authored**Recovery B4 paint**2367.83*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 JUL 2021**SHB9755R**

JTDKB3FU403091190

TOYOTA

PRIUS GEN 4

28/06/2021

AIG

27/11/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	CM 485.61 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>R</i> 332.70 X
1	COVER, REAR BUMPER, LOWER	\$	<i>Sn</i> 22.00 X
1	GUARD, REAR BUMPER, CENTER	\$	<i>Sn</i> 374.50 X
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>Sn</i> 132.60 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sn</i> 132.60 X
1	REFLECTOR ASSY, REFLEX, LH	\$	<i>Sn</i> 39.00 X
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	<i>R</i> 1,294.90 X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	<i>Sn</i> 293.00
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	<i>R</i> 87.10
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	<i>R</i> 98.90
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	<i>nn</i> 21.90
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	<i>nn</i> 34.90
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	<i>nn</i> 15.40
1	MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	<i>Sn</i> 926.00
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	<i>Sn</i> 206.70
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	<i>Sn</i> 339.60
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	<i>Sn</i> 261.00
1	PANEL SUB-ASSY, QUARTER, LH	\$	<i>R</i> 871.50 ✓
1	LINER, REAR WHEEL HOUSE, LH	\$	<i>R</i> 139.80 X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	<i>Sn</i> 175.10 X
1	COVER, REAR FLOOR (CTR)	\$	<i>Sn</i> 229.90 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 651.00 X
TOTAL		\$	7,165.70
25%		\$	1,791.43
		\$	5,374.28

Special Nett*030583**1320**1015-83*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2106-100**SHB9755R**

1SET PARKING AID	\$	<i>Pr</i> 700.00 X
1SET REAR BUMPER CLIP	\$	<i>na</i> 95.00 <i>505a</i>
1 DOOR TRIM CLIP	\$	<i>na</i> 60.00 X
1 DOOR STICKER TEL. NO	\$	<i>na</i> 100.00 <i>605a</i>
1 HUB CAP	\$	<i>Pr</i> 211.50 X
1 RIM	\$	<i>Pr</i> 1,879.40 X
1 TYRE	\$	<i>Pr</i> 350.00 X
1 REAR FENDER CLIP	\$	<i>na</i> 60.00 X
1 REAR FENDER LINER CLIP	\$	<i>na</i> 60.00 X
TOTAL	\$	795.00

TOTAL PARTS \$ 6,169.28**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>100l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>600l</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i> 180.00 X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>na</i> 480.00 X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>na</i> 480.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>na</i> 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2106-100**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9755R

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	<i>301</i>
Towing Fees	\$	<i>nn</i>	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	<i>4401</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>5</i>	220.00	X
To replace, refix and top up coolant for radiator	\$	<i>5</i>	170.00	X
To lift-up / out engine with gear box and refit.	\$	<i>6</i>	440.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>5</i>	380.00	X
TOTAL	\$		9,610.00	
Over All Total	\$		15,779.28	

(PART-BY-PART) Repair Days**25 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: