

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HARISH PRANLAL RUPAWALA
 BLK 102 LENGKONG TIGA #03-393
 SINGAPORE 410102

Contact : 98210051, 96187445

TP AXA.
 Jasper

ESTIMATE

Repair Code : CLM16856
 Date in : 01/07/2021
 Vehicle Num. : SGK8058R
 Model : TOYOTA COROLLA ALTIS 1.6 CVT
 Chassis/Eng# : MR053REH104559132/1ZRY336166

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Buckled</i>	1	793.20	✓ 793.20
REAR BOOTLID 'ALTIS' EMBLEM	1	54.10	✓ 54.10
REAR BOOTLID 'COROLLA' EMBLEM	1	50.20	✓ 50.20
REAR BOOTLID 'LOGO' EMBLEM	1	61.60	✓ 61.60
REAR BOOTLID CHROME MOULDING	1	253.70	+ 253.70
REAR BOOTLID INNER TRIM GARNISH	1	364.30	+ 364.30
REAR BOOTLID LH REFLECTOR	1	374.45	+ 374.45
REAR BOOTLID LH REFLECTOR GASKET SEAL <i>see in</i>	1	43.10	+ 43.10
REAR BOOTLID LOCK STRIKER <i>see in</i>	1	25.00	+ 25.00
REAR BOOTLID MECHANISM LOCK <i>Damaged</i>	1	399.50	✓ 399.50
REAR BOOTLID RUBBER STOPPER <i>see in</i>	4	12.00	+ 48.00
REAR BOOTLID WEATHER STRIP <i>cut</i>	1	184.50	✓ 184.50
REAR BUMPER <i>Damaged</i>	1	581.90	✓ 581.90
REAR BUMPER LH REFLECTOR <i>can be</i>	1	59.80	✓ 59.80
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	399.70	✓ 399.70
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Dented</i>	2	88.20	✓ 176.40
REAR BUMPER REVERSE SENSOR <i>Damaged</i>	2	198.00	✓ 396.00
REAR BUMPER REVERSE SENSOR HOLDER <i>see in</i>	2	43.00	✓ 86.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HARISH PRANLAL RUPAWALA
BLK 102 LENGKONG TIGA #03-393
SINGAPORE 410102

Contact : 98210051, 96187445

ESTIMATE

Repair Code : CLM16856

Date in : 01/07/2021

Vehicle Num. : SGK8058R

Model : TOYOTA COROLLA ALTIS 1.6 CVT

Chassis/Eng# : MR053REH104559132/1ZRY336166

REAR BUMPER SIDE RETAINER L/R <i>crushed</i>	2	109.30	✓	218.60
REAR END PANEL <i>Dented</i>	1	703.50	✓	703.50
REAR END PANEL ANTENNA SENSOR <i>Damaged</i>	1	192.20	✓	192.20
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	241.90	✓	241.90
REAR FLOOR PANEL TOP BOARD COVER <i>torn</i>	1	291.50	✓	291.50
REAR LH FENDER INNER TRIM <i>new</i>	1	338.00	+	338.00
REAR TAILLAMP INNER BLACK RUBBER GASKET L/R <i>new</i>	2	31.20	✓	62.40
REAR TAILLAMP L/R <i>crushed</i>	2	391.90	✓	783.80
REAR TAILLAMP LOWER BRACKET L/R <i>crushed</i>	2	88.70	✓	177.40
Subtotal before discount				7,360.75
Percentage discount 25%				1,840.19
Sub-total 1				5,520.56
REAR BOOTLID CHROME MOULDING CLIPS - SET <i>new</i>	1	30.00	+	30.00
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	40.00	+	40.00
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00	
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	20.00	✓	20.00
REAR LH FENDER INNER TRIM CLIPS - SET <i>new</i>	1	40.00	+	40.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	20.00	✓	40.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HARISH PRANLAL RUPAWALA
BLK 102 LENGKONG TIGA #03-393
SINGAPORE 410102

Contact : 98210051, 96187445

ESTIMATE

Repair Code : CLM16856

Date in : 01/07/2021

Vehicle Num. : SGK8058R

Model : TOYOTA COROLLA ALTIS 1.6 CVT

Chassis/Eng# : MR053REH104559132/1ZRY336166

Subtotal before discount	120	220.00
Percentage discount 0%		0.00
Sub-total 2		220.00
Parts-total		5,740.56

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

✓	60.00
60	120.00
1000 1000	1,200.00
2100	900 1,200.00
✓	80.00
Labour Total	2,660.00
Parts & Labour Total	8,400.56

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
h/s 02/07/21.

06 Days

total: 6655.65

h/s 5.3K ✓