

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA COROLLA ALTIS

Engine/Chassis No.:

Date of accident: 01/07/2021


Damaged area: O/S Front

Date:

09/07/2021

Claim Type: TP

VRN: SJM6750S



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front fender o/s	1	\$ 729.00	\$ 729.00
2	Front fender inner shield o/s	1	\$ 285.00	\$ 285.00
3	Headlamp o/s	1	\$ 1,165.00	\$ 1,165.00
4	Headlamp lower bracket o/s	1	\$ 109.00	\$ 109.00
5	Front bumper	1	\$ 769.00	\$ 769.00
6	Front bumper lower splash cowling	1	\$ 396.00	\$ 396.00
7	Front bumper side retainer	2	\$ 84.00	\$ 168.00
8	Front bumper foglamp o/s	1	\$ 287.00	\$ 287.00
9	Front bumper foglamp outer garnish o/s	1	\$ 76.00	\$ 76.00
10	Front bumper lower grille	1	\$ 365.00	\$ 365.00
11	Radiator grille bracket	1	\$ 147.00	\$ 147.00
12	Front shock absorber o/s	1	\$ 389.00	\$ 389.00
13	Front shock absorber mounting o/s	1	\$ 95.00	\$ 95.00
14	Front lower arm o/s	1	\$ 487.00	\$ 487.00
15	Front wheel knuckle o/s	1	\$ 398.00	\$ 398.00
16	Front wheel knuckle bearing o/s	1	\$ 185.00	\$ 185.00
17	Front bumper reinforcement	1	\$ 377.00	\$ 377.00
18	Drive shaft o/s	1	\$ 689.00	\$ 689.00
19	Air intake hose	1	\$ 243.00	\$ 243.00
20	Coolant expansion tank	1	\$ 195.00	\$ 195.00
21	Front fender inner top bracket o/s	1	\$ 218.00	\$ 218.00
22	Anti roll bar	1	\$ 335.00	\$ 335.00
23	Anti roll bar bracket	2	\$ 45.00	\$ 90.00
24	Anti roll bar bracket bushing	2	\$ 25.00	\$ 50.00
25	Anti roll bar endlink	2	\$ 155.00	\$ 310.00
26	Cross member	1	\$ 1,673.00	\$ 1,673.00
27	Cross member bushing	6	\$ 65.00	\$ 390.00
28	Steering rack assy	1	\$ 1,556.00	\$ 1,556.00
29	Tie rod end	2	\$ 89.00	\$ 178.00
30	Bonnet	1	\$ 980.00	\$ 980.00

Repair Estimate

31	Bonnet lock	1	\$ 295.00	\$ 295.00
Subtotal				\$ 13,629.00
List discount				25.00%
Total				\$ 10,221.75

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips	12	\$ 5.50	\$ 66.00
2	Front fender inner shield clips o/s	8	\$ 5.50	\$ 44.00
3	Front bumper lower splash cowling clips	8	\$ 5.50	\$ 44.00
4	Front alloy rim o/s	1	\$ 450.00	\$ 450.00
5	Front tyre o/s	1	\$ 280.00	\$ 280.00
6	Radiator coolant	1	\$ 80.00	\$ 80.00
9	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,014.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and refit n/s front tyre & rims. To perform tyre balancing.	0.25	\$ 50.00
4	To remove and refit n/s front undercarriage for replacement of parts.	1	\$ 200.00
5	To conduct computerized wheel alignment.	0.5	\$ 100.00
6	Supply spray paint material and necessary items to respray affected area / panel.	7	\$ 1,400.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,300.00

Estimate Grand Total	\$ 14,535.75
-----------------------------	---------------------