

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5787U

AAD2107-

*Not Authorized
Recovery B4 paint
7155.53*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 JUL 2021

010 JUL 2021

SHC5787U

JTDKB3FU903091511

TOYOTA

PRIUS GEN 4

01/07/2021

Tokio -

16/09/2020

PART**LIST**

1	FENDER SUB-ASSY, FRONT RH		R	977.8	✓
1	LINER, FRONT FENDER, RH		Sn	202.5	X
1	EMBLEM, SIDE PANEL, RH		R	54.6	✓
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	R	1,300.70	✓
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH		Det	603.2	✓
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH		R	38.6	✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	DIY	193.50	✓
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	DIY	390.60	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	R	926.00	X
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	DIY/R	321.10	✓
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R	110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R	97.50	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	R	238.30	X
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	R	43.50	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	R	13.30	✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	R	26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	R	1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH		Sn	193.5	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH		Sn	97.4	X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	Sn	293.00	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	Sn	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	Sn	206.70	X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	R	34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	R	15.40	✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	R	21.90	✓

REF: *Tm / 2*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2107-

SHC5787U

1	HINGE ASSY, REAR DOOR, LOWER RH	\$	<i>11</i>	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	<i>11</i>	98.90	✓
1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>12</i>	871.50	✓
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>12</i>	139.80	X
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>12</i>	594.80	X

TOTAL	\$	9,179.00
25%	\$	2,294.75
	\$	6,884.25

Special Nett

1	REAR FENDER LINER CLIP	\$	<i>na</i>	65.00	X
1	REAR BUMPER RETAINER CLIP	\$	<i>na</i>	75.00	X
1	HUB CAP	\$	<i>na</i>	211.50	X
1	RIM	\$	<i>na</i>	1,879.40	X
1	DOOR STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>6500</i>
1	DOOR STICKER TEL NO	\$	<i>na</i>	100.00	<i>6500</i>
1	DOOR TRIM CLIP	\$	<i>na</i>	75.00	X
1	DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	80.00	X

TOTAL	\$	2,585.90
--------------	----	-----------------

TOTAL PARTS	\$	9,470.15
--------------------	----	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ 240.00 *900*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 *1000*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 1,600.00 *1000*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair. \$ *na* 380.00 X

Trans-cab Auto Services Pte Ltd

AAD2107-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5787U

Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	1100/
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	5,100.00	
Over All Total	\$	14,570.15	

(PART-BY-PART) Repair Days**20 Days***8 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: