



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

EQ Insurance Company Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/06/2021
Vehicle Reg. No.:	XE4345T	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HINO GH1JPLA, 8.0 D (M)	Vehicle Reg. Date:	28/09/2018
Vehicle Colour:	WHITE	Chassis No:	JHDGH8JR1XXX10213
Engine No:	J08EWS10155		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	5,645.43
Miscellaneous Items	0.00
Labour	1,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	7,445.43
+ GST 7.00% (\$)	521.18
Nett Amount (\$)	7,966.61

This claim is handled by: **BILLY**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 02 Jul 2021)	
Parts:	N/A	HINO GH1JPLA 8.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE4345T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILLAMP ASSY LH	0.00	0.00	*180.10 F
2	1		*REAR CHASSIS FRAME LH (REPAIR)	0.00	0.00	-
3	1		*REAR STEP PANEL	0	0.00	*800.00 FS
4	1		*REVERSE LAMP BRACKET	0	0.00	*60.00 FS
5	1		*REVERSE LAMP LH	0.00	0.00	*71.20 F
6	1		*WOODEN TAILLAMP	0	0.00	*1,000.00 FS
7	1		*WOODEN TAILGATE LOCK LH	0	0.00	*150.00 FS
8	1		*WOODEN SIDE GATE LH	0	0.00	*1,600.00 FS
9	1		*FRONT WOODEN GATE	0	0.00	*1,000.00 FS
10	1		*COMPANY STICKER	0.00	0.00	*680.00 F
11	1		*60 KM/H STICKER	0.00	0.00	*10.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	5,551.30
+ Margin on L,N Items 10.00% (\$)	94.13
Total Parts (\$)	5,645.43

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REAR WOODEN PLATFORM IN ORDER TO KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER, CUT/WELD REAR STEP PANEL, REMOVE & REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION	New	1,500.00
2	SPRAY PAINT REAR STEP PANEL, REAR BRACKET	New	300.00
Gross Labour Cost (S\$)			1,800.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >