

2/2021

REPAIR DETAILS

Estimate Report

Reference

Part Source:

Parts: N/A

(Last Synchronised: 02 Jul 2021)

Labour: Repairer's

HINO GH1JPLA 8.0 D (M) (Model not available in database)

Print Code: (Unsubmitted, no print-code for XE4345T)

(Price-denominated Standard List)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILLAMP ASSY LH / BR	0.00	0.00	*180.10 F / P
2	1		*REAR CHASSIS FRAME LH (REPAIR) X R	0.00	0.00	-
3	1		*REAR STEP PANEL X nn	0	0.00	*800.00 FS
4	1		*REVERSE LAMP BRACKET X nn	0	0.00	*60.00 FS
5	1		*REVERSE LAMP LH X nn	0.00	0.00	*71.20 F
6	1		*WOODEN TAILLAMP (tailgate) / DO	0	0.00	*1,000.00 FS N
7	1		*WOODEN TAILGATE LOCK LH / mis	0	0.00	*150.00 FS N
8	1		*WOODEN SIDE GATE LH X nn	0	0.00	*1,600.00 FS
9	1		*FRONT WOODEN GATE / BR	0	0.00	*1,000.00 FS N
10	1		*COMPANY STICKER / ACC	0.00	0.00	*680.00 F N
11	1		*60 KM/H STICKER / ACC	0.00	0.00	*10.00 F N

F=Franchise part. S=SpcNett.

Sub Total (S\$) 5,551.30
+ Margin on L,N Items 10.00% (S\$) 94.13
Total Parts (S\$) 5,645.43

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

P - 180 N - 1150
- 10%
162

L - 1250

= 2562

L/S - 2049.60

= 2050

7/2/2021

Estimates on Miscellaneous Items

Estimate Report

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type Amount

Labour Items

1	TO REMOVE & REAR WOODEN PLATFORM IN ORDER TO KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER, CUT/WELD REAR STEP PANEL, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	1000	1,500.00
2	SPRAY PAINT REAR STEP PANEL, REAR BRACKET	New	250	300.00
Gross Labour Cost (\$)				1,800.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

L - 1250

Stenc (CLKK) with P.L
5/7/21, 30pp
L/S
5 dys
My PL sy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: