



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21007299/Atf3n2	
			Date: 14/09/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBE 1682A	Veh. Inspected	SMZ 1073S
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101949/LOR	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA6	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JM6GJ1072G0208645	Colour	BLACK
	Odometer	107394 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	MICHELIN	6 mm
	L/H Front Tyre	225/55 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/55 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/55 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/06/2021	Inspection Date	05/07/2021
	Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	