

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%20	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	24k

TO: SOOMPO
Vehicle No : SMZ 1073 S
Make & Model : MAZDA 6
DATE: 30/6/2021

IM6GJ1072G0208645

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BOOT LID <i>Repair</i>	1	\$ 1,215.80	\$ + 1,215.80
2	BOOT LID EMBLEM	1	\$ 108.90	\$ ☒ 108.90
3	BOOT LID EMBLEM (MAZDA 6)	1	\$ 94.70	\$ ☒ 94.70
4	BOOT LID EMBLEM (SKYACTIVE)	1	\$ 87.50	\$ ☒ 87.50
5	BOOT LID LAMP RH <i>cracked</i>	1	\$ 796.30	\$ ☒ 796.30
6	BOOT LID CENTER CHROME <i>Not in</i>	1	\$ 452.50	\$ + 452.50
7	BOOT LID SIDE CHROME RH <i>cracked</i>	1	\$ 317.00	\$ ☒ 317.00
8	BOOT LID CAR PLATE LAMP <i>Not in</i>	2	\$ 89.00	\$ + 178.00
9	BOOT LID CAR PLATE LAMP GARNISH <i>Not in</i>	1	\$ 112.00	\$ + 112.00
10	BOOT LID OPENER HANDLE <i>Not in</i>	1	\$ 177.80	\$ + 177.80
11	BOOT LID LOCK ASSY <i>Not in</i>	1	\$ 280.40	\$ + 280.40
12	BOOT LID LOCK CATCH <i>Not in</i>	1	\$ 56.20	\$ + 56.20
13	BOOT LID WEATHERSTRIP <i>Not in</i>	1	\$ 172.80	\$ + 172.80
14	BOOT LID DETECTOR <i>Not in</i>	1	\$ 277.00	\$ + 277.00
15	REVERSE CAMERA <i>Not in</i>	1	\$ 954.00	\$ + 954.00
16	TAILLAMP RH <i>cracked</i>	1	\$ 1,592.00	\$ ☒ 1,592.00
17	TAILLAMP PANEL RH <i>Repair</i>	1	\$ 254.00	\$ + 254.00
18	REAR BUMPER <i>Deformed</i>	1	\$ 1,266.90	\$ ☒ 1,266.90
19	REAR BUMPER SIDE RETAINER RH <i>Replaced</i>	2	\$ 79.80	\$ 79.80 159.60
20	REAR BUMPER REFLECTOR RH <i>Not in</i>	1	\$ 154.30	\$ + 154.30
21	REAR BUMPER REVERSE SENSOR RH <i>Deformed</i>	1	\$ 351.00	\$ ☒ 351.00
22	REAR BUMPER TOWING COVER <i>Not in</i>	2	\$ 58.30	\$ + 116.60
23	REAR BUMPER CENTER BRACKET <i>Not in</i>	1	\$ 19.80	\$ + 19.80
24	REAR BUMPER REINFORCEMENT <i>Not in</i>	1	\$ 588.30	\$ + 588.30
25	REAR BUMPER SIDE COVER RH <i>Not in</i>	1	\$ 72.30	\$ + 72.30
26	REAR END PANEL <i>Repair</i>	1	\$ 788.90	\$ + 788.90

27	REAR END PANEL TOP GARNISH <i>Not m</i>	1	\$ 180.10	\$ X 180.10
28	REAR FLOOR PANEL TOP BOARD <i>Not m</i>	1	\$ 498.00	\$ X 498.00
29	REAR FLOOR PANEL TOOLS SPONGE RH <i>Not m</i>	1	\$ 168.00	\$ X 168.00
30	REAR FENDER RH <i>Dented</i>	1	\$ 1,310.00	\$ ✓ 1,310.00
31	REAR FENDER INNER TRIM RH <i>Not m</i>	1	\$ 544.60	\$ X 544.60
32	REAR FENDER INNER COWLING RH <i>Not m</i>	1	\$ 159.00	\$ X 159.00
33	REAR FENDER QUARTER GARNISH RH <i>lit</i>	1	\$ 185.00	\$ ✓ 185.00
34	REAR FENDER AIR VENT RH <i>Not m</i>	1	\$ 54.00	\$ X 54.00
35	REAR SPORT RIM RH <i>lit</i>	1	\$ 1,121.00	\$ 607.50 1,121.00
36	REAR ABSORBER RH	1	\$ 677.00	\$ X 677.00
37	REAR LOWER ARM RH	1	\$ 689.00	\$ X 689.00
38	REAR KNUCKLE ARM RH	1	\$ 675.40	\$ X 675.40
39	REAR WHEEL BEARING RH	1	\$ 321.00	\$ X 321.00
40	REAR EXHAUST SILENSER	1	\$ 1,745.00	\$ X 1,745.00
41	REAR EXHAUST MOUNTING	2	\$ 19.20	\$ X 38.40
42	REAR EXHAUST HEAT SHIELD	1	\$ 254.00	\$ X 254.00
43	REAR DOOR RH <i>Dented</i>	1	\$ 1,312.00	\$ 1,312.00 1,312.00
44	REAR DOOR OUTER MOULDING RH <i>lit</i>	1	\$ 287.00	\$ ✓ 287.00
45	REAR DOOR TOP FRAME CHROME MOULDING RH <i>lit</i>	1	\$ 315.00	\$ ✓ 315.00
46	REAR DOOR GLASS RH <i>lit</i>	1	\$ 675.30	\$ ✓ 675.30
47	REAR DOOR QUARTER GLASS RH <i>lit</i>	1	\$ 335.00	\$ ✓ 335.00
48	REAR DOOR BLACK STICKER RH <i>lit</i>	1	\$ 45.00	\$ ✓ 45.00
49	REAR DOOR OUTER STRIP <i>Not m</i> <i>lit</i>	1	\$ 325.00	\$ X 325.00
50	REAR DOOR OUTER HANDLE RH <i>Not m</i>	1	\$ 249.10	\$ X 249.10
51	ROCKER PANEL RH <i>Repis</i>	1	\$ 845.00	\$ X 845.00
52	FRONT DOOR RH <i>Repis</i>	1	\$ 1,312.00	\$ X 1,312.00
53	FRONT DOOR SIDE MIRROR <i>Dented</i>	1	\$ 785.00	\$ ✓ 785.00
54	FRONT DOOR OUTER MOULDING RH <i>lit</i>	1	\$ 287.00	\$ ✓ 287.00
55	FRONT DOOR TOP FRAME CHROME MOULDING RH <i>lit</i>	1	\$ 315.00	\$ ✓ 315.00
56	FRONT DOOR GLASS RH <i>Not m</i>	1	\$ 675.30	\$ X 675.30
57	FRONT DOOR BLACK STICKER RH <i>Not m</i> <i>lit</i>	1	\$ 45.00	\$ ✓ 45.00
58	FRONT DOOR OUTER STRIP <i>Not m</i>	1	\$ 325.00	\$ X 325.00

S.N. 600

Subtotal : \$ 23,158.50

Less 20% \$ 4,631.70

Parts Total : \$ 18,526.80

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR NUMBER PLATE <i>Not m</i>	1	\$ 80.00	\$ X 80.00
2	REAR BUMPER CLIP SET <i>Not m</i>	1	\$ 50.00	\$ 30 50.00
3	TAIL LAMP CLIP SET <i>Not m</i>	1	\$ 30.00	\$ 10 30.00

4	REAR WINDSCREEN SEALANT <i>3m</i>	1	\$	80.00	\$ 140 80.00
5	REAR WINDSCREEN INNER SEAL	1	\$	60.00	\$ 30 60.00
6	REAR FENDER SEALANT <i>Nur</i>	1	\$	80.00	\$ 40 80.00
7	REAR FENDER QUARTER GAENISH CLIPS <i>new</i>	1	\$	30.00	\$ 5 30.00
8	REAR FENDER INNER COWLING CLIP <i>3m</i>	1	\$	40.00	\$ 5 40.00
9	REAR FENDER INNER TRIM RH CLIP SET	1	\$	50.00	\$ 5 50.00
10	REAR END PANEL SEALANT <i>7m</i>	1	\$	80.00	\$ X 80.00
11	REAR DOOR SEALANT <i>new</i>	1	\$	80.00	\$ X 80.00
12	ROCKER PANEL SEALANT <i>new</i>	1	\$	120.00	\$ X 120.00

SPECIAL NETT

\$ **780.00**

LABOUR (REAR)		PRICE	
PANEL BEATING, REMOVAL AND REPLACING PARTS	<i>1000</i>	\$	1,800.00
TO SPRAY PAINT AFFECTED AREA	<i>1000</i>	\$	1,600.00
APPLY TUFF COATING TREATMENT.		\$	X 600.00
DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	<i>X</i>	\$	150.00
REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.		\$	50 80.00
DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.		\$	80 400.00
REMOVE AND INSTALL REAR WINDSCREEN		\$	120 200.00
REMOVE AND INSTALL REAR DOOR PART		\$	80 200.00
PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.		\$	30 100.00
REMOVE AND INSTALL REAR UNDER CARRIAGE		\$	X 600.00
REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY. PERFORM AIMING AND ADJUST TO POSITION.		\$	X 120.00
TO CHECK FOUR WHEEL ALIGHMENT		\$	80 150.00
CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.		\$	X 150.00
TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY. RE-ALIGN TO POSITION.		\$	X 150.00
<i>2440</i>			
LABOUR TOTAL		\$	6,300.00

Total Parts Cost	\$	19,306.80
Total Labour Cost	\$	6,300.00
Total Repair Cost	\$	25,606.80

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Adrian Lj
n/s 05/07/21

08 Days .

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: