

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NETT ITEM

VEHICLE No: SGV 2176P

1PC	BOOTLID	20/Buc	684	\$845.00	—
1PC	BOOTLID OUTER GARNISH	one	197	\$299.00	—
1PC	BOOTLID INNER LOCK	sent	168	\$195.00	—
1PC	BOOTLID WEATHERSTRIP	1w1	166	\$266.00	—
1PC	BOOTLID REAR LOGO	all		\$48.00	—
1PC	BOOTLID 'MITSUBISHI' EMBLEM	all	42	\$60.00	—
1PC	BOOTLID 'LANCER' EMBLEM	all	54	\$52.00	—
2PCS	BOOTLID HINGES @ \$165.00	R		\$330.00	X
1PC	REAR BUMPER	20	696	\$801.00	—
1PC	REAR BUMPER BEAM	sent	174	\$195.00	—
2PCS	REAR BUMPER SIDE RETAINERS @ \$65.00	MS sent		\$130.00	1PG
1SET	REAR BUMPER CLIPS	all		\$50.00	—
1PC	REAR END PANEL	20	442	\$580.00	—
1PC	REAR END PANEL TOP GARNISH	1w1	161	\$265.00	—
1PC	REAR FLOOR PANEL	R		\$991.00	X
1PC	REAR FLOOR PANEL TOP BOARD	Torn	175	\$365.00	—
2PCS	TAILLAMPS @ \$445.00	one	404x2=808	\$890.00	—
2PCS	REAR FENDERS @ \$885.00	R		\$1,770.00	X
2PCS	REAR FENDER INNER TRIMS \$366.00	2w1 torn	10% 232x2=	\$732.00	464
				\$8,864.00	

S.NETT

1PC	REAR END PANEL SEALANT	all	\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	11	\$280.00	X
1PC	REAR END PANEL SEALANT	Repeated	\$50.00	X

TO CHECK WIRING

TO DISMANTLE & REPLACED REVERSE SENSOR

TO TRANSFER BOOTLID MECHANISM

TO DISMANTLE & REFIX CUSHION UPHOLSTERY

TO DISMANTLE & REFIX REAR EXHAUST

TO SPRAY RUST PROOFING

TO DISMANTLE & REFIX REAR WINDSCREEN

TO DISMANTLE & REFIX FUEL TANK

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

TOTAL

\$80.00	20
\$80.00	X
\$80.00	60
\$120.00	80
\$100.00	X
\$100.00	60
\$120.00	X
\$100.00	X
\$1,800.00	800
\$1,800.00	1000
\$13,624.00	

Uth-Hsiao Tung

P-4394
6024.6