


MBM WHEELPOWER PTE LTD



Your Ref: EV36Y
Our Ref: SMQ9585B

To: MSIG

CC

Fax

*Not with the
Return B4 paint
5 days
84897-28*

Date: 2/7/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA ALPHARD 2.5
Chassis No.: AGH300246845
Engine No.: 2ARJ279933
Year of Make: 2019
Accident Date: 1 July 2021

ESTIMATE FOR VEHICLE NO.: SMQ9585B

DESCRIPTION

FRONT BUMPER
FRONT BUMPER RH SIDE RETAINER
FRONT BUMPER RH CHROME *118*
HEAD LAMP RH *3831.70*
HEAD LAMP RH CHROME
FRONT RH FENDER
BUMPER CLIPS

QTY

List Price

1	\$	<i>Sn</i> 2,250.00 <i>X</i>
1	\$	<i>Orl</i> 95.00 <i>✓</i>
1	\$	<i>CM</i> 210.00 <i>✓</i>
1	\$	<i>MJCM</i> 4,050.00 <i>✓</i>
1	\$	<i>MJCM</i> 210.00 <i>✓</i>
1	\$	<i>Bu</i> 680.00 <i>✓</i>
10	\$	<i>nn</i> 60.00 <i>X</i>
Total: \$		7,555.00
LESS 25% \$		(1,888.75)
Parts Total: \$		5,666.25

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
TO APPLY ANTI RUST COATING
TO REMOVE & REPLACE BUMPER SENSORS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO SPRAY PAINT ON THE AFFECTED AREAS

\$	<i>4001</i> 1,000.00
\$	<i>nn</i> 300.00 <i>X</i>
\$	<i>301</i> 150.00
\$	<i>nn</i> 60.00 <i>X</i>
\$	80.00 <i>201</i>
\$	<i>6601</i> 1,000.00

Total: \$ 8,256.25

7% GST: \$ 577.94

Grand Total: \$ 8,834.19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62628888 f 64525333

Company Registration Number : 200204110W