

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBR4215C MODEL : YAMAHA XMAX 300

Handle Bar *Not in*
 Mirror SET(RH) *lit*
 Lever Set *lit*
 Balancer set *new*
 Wind Screen *Missing*
 Wind Screen Holder *new*
 Top Belting Cover *lit*
 Lower Belting Cover *lit*
 Head Light *lit*
 Fairing Stay *Best*
 Front Fairing RH *could*
 Signal Light RH *could*
 Signal Light Garnish *lit*
 Foot Paddle Top RH *Delnd*
 Foot Paddle Lower RH *lit*
 Side Fairing RH *could*
 Fork Inner Tube *Best*
 Fork Outer Tube *RH lit*
 Fork Protractor RH *could*
 Fork Lower Clamp *2nd*
 Steering Cone *2nd*
 Disc *warpped*
 Rim *new*
 Seat Bar *lit*
 Side Cover RH *could*
 Box *lit*
 Exhaust Pipe *Attn Dented*
 Exhaust Pipe Cover *could*
 Rear Footrest RH *lit*
 Main Stand *new*
 Rear Absorber *Best*
 Rear Engine Mounting *torn*
 Rear Body Frame Repair
 Rear Body Frame Respray
 Fairing Respray
 Logo *new*
 Front Number Plate *Missing*
 labour
 transport

LKK Auto Consultants hence notify

the Register of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

90

96

80

280

98

85

85

580

180

220

75

65

78

78

280

450

550

155

420

130

180

650

180

185

180

580

220

78

150

660

480

380

350

550

80

35

550

50

9768

250

550

275

155

420

130

180

650

180

185

180

580

220

78

150

660

480

380

350

550

80

35

550

50

9768

Parts: 6233

Len 10%: \$609.70

S.N: 115

Labour: 920

total: 6644.70

Admin Lj

P/P 06/07/21

05 Days