

ASS. REC. BY: Tang Jkh

REF: CC4/M1621007309/Tig93.

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SNC6362E Yr Regn: 2015, Jan.
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Kia Optima c.c. 1685
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 641510 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RNA6M414MF5575304
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: 0 Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/65R15
R: 205/65R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Maxxis
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 5/7/21
Survey held at Premia Auto
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Rep. Format: _____
Lump Sum / L.B.H. ()

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S + RS. _____ SI	
Photos	
Others	
TOTAL	

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Jul-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6362 E

1 pc	Front o/s head lamp	\$ 1,028.00	car
1 pc	Front bumper emblem	\$ 44.00	car
1 pc	Front bumper	\$ 531.00	de
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$ n/sx 32.00	o/s de
2 pcs	Front bumper n/s & o/s upper bracket @ \$16.00	\$ n/sx 32.00	o/s
2 pcs	Front bumper n/s & o/s support bracket @ \$16.00	\$ n/sx 32.00	o/s
1 pc	Front bumper reinforcement	\$ 328.00	x
1 pc	Front bumper sponge	\$ 110.00	x
1 pc	Front bumper o/s protector	\$ 51.00	ant-
1 pc	Front bumper o/s fog lamp cover	\$ 66.00	?
1 pc	Front bumper lower stiffer	\$ 134.00	x
1 pc	Front bumper lower lip	\$ 40.00	?
1 pc	Front bumper centre grille	\$ 174.00	x
1 pc	Washer tank	\$ 47.00	de-
1 pc	Washer tank motor	\$ 48.00	?
1 pc	Support panel	\$ 645.00	bl-
1 pc	Bonnet	\$ 979.00	bl-
1 pc	Bonnet hinge @ \$47.00	\$ 94.00	Rx
1 pc	Bonnet grille	\$ 385.00	x
1 pc	Front o/s fender	\$ 384.00	bt-
1 pc	Front o/s fender inner shield	\$ 120.00	tr
1 pc	Front o/s wheel house	\$ 474.00	Rx
1 pc	Front o/s lower arm	\$ 439.00	?
1 pc	Front o/s shock absorber	\$ 330.00	?
1 pc	Front o/s ball joint	\$ 59.00	x
1 pc	Front o/s tie rod end	\$ 61.00	x
1 pc	Front o/s knuckle bearing	\$ 157.00	?
1 pc	Front o/s stabilizer link	\$ 86.00	x
1 pc	Front o/s knuckle arm	\$ 547.00	?
1 pc	Front o/s rim	\$ 246.00	x
1 pc	Front o/s wheel cover	\$ 116.00	ant
		\$ 7,819.00	
Less 10%		\$ 781.90	
		\$ 7,037.10	

5-Jul-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6362 E

S/NETT

1 set	Front o/s fender inner shield clips	\$	28.00 <i>16 net</i>
1 set	Front bumper clips	\$	48.00 <i>30 net</i>
1 pc	Front o/s fender sticker	\$	60.00 <i>40 net</i>
	<i>Front o/s door sticker</i>		<i>\$600 50 net</i>
	Towing Fee	\$	50.00 ✓
	To check wheel alignment	\$	80.00 ✓
	To dismantle and replace front o/s undercarriage	\$	250.00 <i>150? plus</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
	To lift engine to facilitate repair on the front o/s wheel house	\$	350.00 <i>200? plus</i>
	To dismantle the dashboard to facilitate repair on the front o/s wheel house	\$	350.00 <i>180? plus</i>
	To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the front o/s wheel house. Including knock-out, straighten, repair, reshape and adjust of the front o/s chassis member same etc	\$	1,200.00 <i>700</i>
	To putty and spray painting on front bumper, bonnet, bonnet grille, front o/s fender, front o/s wheel house, front o/s chassis member	\$	1,200.00 <i>900</i>
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 <i>30</i>
		\$	<u>11,033.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
WP' 5/7/21 & 14/1720
6 days
1/2 Resurvey after repair
further information.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	20 Jan 2015 / 09:09:27	Receipt No.:	AACCK001-AX239-150120-000010
Asset Type:	Vehicle	Transaction Amount:	\$66,097.00
Asset ID:	SHC6362E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150120090927878850		
Vehicle No.:	SHC6362E		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	20 Jan 2015		
Original Registration Date:	20 Jan 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5575304		
Engine No.:	D4FDEH313236		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$20,693.00		
Minimum PARF Benefit:	\$8,082.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	20 Jan 2015 09:09:27		
COE No.:	2015012001001509N		
COE Expiry Date:	19 Jan 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$52,486.00		
Lifespan Expiry Date:	19 Jan 2023		



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Email: peoplevehicle@gmail.com

Reg No: 200415052W



Date: 5.8.21

CASH SALEWORK ORDER No: PA 1494

寶號: Paulo (P17)

車號: SHC 6362 E 車型: KIA optima

由: 133 Redok Reservoir RD

到: Paulo Omega level 1

其他: 1 Key

時間: 08:22:09:15:09:46 AMOUNT: \$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

經手人: [Signature] 4363 收貨人: [Signature]

Authorised by: Received by:

- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ Jump Start
- ☐ Changing of Battery
- ☐ Tyre Replacement/ Patching
- ☐ Crane Up/Winch Out
- ☐ With Load/Cargo Box
- ☐ Flat Bed
- ☐ King Dolly to lift up
- ☐ Low Body Kit
- ☐ Repo
- ☐ Door Opening Service
- ☐ Collect Document/Key
- ☐ Jurong Island/Cargo Complex
- ☐ Woodlands/Tuas Checkpoint
- ☐ Cancellation Charge (Reach Location)
- ☐ Cancellation Charge (After 15 minutes)