

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Jul-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6362 E

1 pc	Front o/s head lamp	\$ 1,028.00	an
1 pc	Front bumper emblem	\$ 44.00	an
1 pc	Front bumper	\$ 531.00	de
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$ n/s x ⁿⁿ 32.00	o/s de
2 pcs	Front bumper n/s & o/s upper bracket @ \$16.00	\$ n/s x ⁿⁿ 32.00	o/s nec
2 pcs	Front bumper n/s & o/s support bracket @ \$16.00	\$ n/s x ⁿⁿ 32.00	o/s w
1 pc	Front bumper reinforcement	\$ 328.00	x nn
1 pc	Front bumper sponge	\$ 110.00	x n1
1 pc	Front bumper o/s protector	\$ 51.00	ant-
1 pc	Front bumper o/s fog lamp cover	\$ 66.00	? der
1 pc	Front bumper lower stiffer	\$ 134.00	x nn
1 pc	Front bumper lower lip	\$ 40.00	? de
1 pc	Front bumper centre grille	\$ 174.00	x nn
1 pc	Washer tank	\$ 47.00	de
1 pc	Washer tank motor	\$ 48.00	x nn
1 pc	Support panel	\$ 645.00	bc
1 pc	Bonnet	\$ 979.00	bc
1 pc	Bonnet hinge @ \$47.00	\$ 94.00	Rp
1 pc	Bonnet grille	\$ 385.00	x nn
1 pc	Front o/s fender	\$ 384.00	st-
1 pc	Front o/s fender inner shield	\$ 120.00	tr
1 pc	Front o/s wheel house	\$ 474.00	Rp
1 pc	Front o/s lower arm	\$ 439.00	? }
1 pc	Front o/s shock absorber	\$ 330.00	? }
1 pc	Front o/s ball joint	\$ 59.00	x }
1 pc	Front o/s tie rod end	\$ 61.00	x }
1 pc	Front o/s knuckle bearing	\$ 157.00	? } nt
1 pc	Front o/s stabilizer link	\$ 86.00	x }
1 pc	Front o/s knuckle arm	\$ 547.00	? }
1 pc	Front o/s rim	\$ 246.00	x }
1 pc	Front o/s wheel cover	\$ 116.00	an
		\$ 7,819.00	4099
Less 10%		\$ 781.90	3689.10
		\$ 7,037.10	

5-Jul-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6362 E

S/NETT

1 set Front o/s fender inner shield clips
1 set Front bumper clips
1 pc Front o/s fender sticker

Front o/s door sticker \$600 50 net

Towing Fee

To check wheel alignment

To dismantle and replace front o/s undercarriage

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To lift engine to facilitate repair on the front o/s wheel house

To dismantle the dashboard to facilitate repair on the front o/s wheel house

To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the front o/s wheel house. Including knock-out, straighten, repair, reshape and adjust of the front o/s chassis member same etc

To putty and spray painting on front bumper, bonnet, bonnet grille, front o/s fender, front o/s wheel house, front o/s chassis member

To apply rustproofing on the repaired and replaced panels.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

\$ 28.00 10 net
\$ 48.00 30 net
\$ 60.00 40 net

130

\$ 50.00 ✓

\$ 80.00 ✓

\$ 250.00 50? X
plus.

\$ 180.00 X net

\$ 350.00 X net 200? plus.

\$ 350.00 100? plus.

\$ 1,200.00 700

\$ 1,200.00 900

\$ 200.00 30 1760

\$ 11,033.10

3689.10

130

1760

5579.10

4594450

05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

WP 5/7/21 @ 14/1720

5 days

1/2 Resurvey after repair
further 1/2 hours.