



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21007322/Dqf3e2	
			Date: 23/07/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SHB 834E	Veh. Inspected	SKW 6026K	
Policy No.	D-20095484MFSH	Coverage (\$)	0.00	
Claim No.	D21000924MFSH	Excess (\$)	0.00	
Assign From	ESTHER LIM	Assign Date	02/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE MACAN	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WP1ZZZ95ZGLB05649	Colour	BLUE	
Odometer	60598 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	MICHELIN	5 mm	
L/H Front Tyre	235/60 R18	MICHELIN	5 mm	
R/H Rear Tyre	235/60 R18	MICHELIN	5 mm	
L/H Rear Tyre	235/60 R18	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	23/03/2021	Inspection Date	08/07/2021	
Survey held at	Blk 10, Ang Mo Kio Ind Park 2A, #02-16			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			16 Working Days	