

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007328/UGS3Q2**Date:** 17/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210003060
Claimant Vehicle No :	FBL6844E	Insured Vehicle No :	SMY183U
Date of Loss:	29/04/2021	Nature of Claim:	TP
		Claim No:	0675875867SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL6844E	Engine No:	G3E6E0242287
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740G0041396
Reg. Date:	24/01/2017 (Man. Year: 2016)	Odometer:	0 km
Colour:	White		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	110/70-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,968.60	2,678.30	3,290.30	55.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	330.00	630.00	65.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,928.60	3,008.30	3,920.30	56.58
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	05/07/2021	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	05/07/2021 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	*Check	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	*Check	205.00 FL	*- FL
3	1		*FRONT WHEEL RIM	Repair	320.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	95.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	52.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	185.00 FL	*- FL
7	1		*METER ASSY	Cut	625.00 FL	*625.00 FL
8	1		*HEADLAMP	*Check	280.00 FL	*- FL
9	1		*SET MIRROR	Broken	180.00 FL	*180.00 FL
10	1		*HANDLE -BAR	*Check	102.00 FL	*- FL
11	1		*HANDLE -BAR END (N/S)	Cut	95.00 FL	*95.00 FL
12	1		*HANDLE -FRONT COVER	Cut	105.00 FL	*105.00 FL
13	1		*HANDLE REAR COVER	Not Necessary	85.00 FL	*- FL
14	1		*FRONT HORN INNER COVER CENTRE BLACK	*Check	78.00 FL	*- FL
15	1		*FRONT SIGNALS	Not Necessary	150.00 FL	*- FL
16	1		*BRAKE LEVER	Cut	65.00 FL	*65.00 FL
17	1		*SET FAIRING ASSY	Cracked	560.00 FL	*560.00 FL
18	1		*FRONT SIDE LOWER COVER	Distorted	160.00 FL	*160.00 FL
19	1		*SET FRONT FOOTREST BRACKET	Bent	98.00 FL	*98.00 FL
20	1		*BRAKE PEDAL	Bent	65.00 FL	*65.00 FL
21	1		*GEAR PEDAL	Bent	58.00 FL	*58.00 FL
22	1		*SET REAR FOOTREST	Not Necessary	88.00 FL	*- FL
23	1		*REAR FOOTREST BRACKET	Not Necessary	98.00 FL	*- FL
24	1		*EXHAUST ASSY	Not Necessary	520.00 FL	*- FL
25	1		*EXHAUST PROTECTOR -FRONT	Not Necessary	52.00 FL	*- FL
26	1		*EXHAUST PROTECTOR -REAR (Scratched)	Not Consistent With The Impact	72.00 FL	*- FL
27	1		*EXHAUST PIPE END COVER (Scratched)	Not Consistent With The Impact	65.00 FL	*- FL
28	1		*REAR FENDER BRACKET	Bent	78.00 FL	*78.00 FL
29	1		*REAR RIM SHAFT	Cut	98.00 FL	*98.00 FL
30	1		*SET NUMBER PLATE	FRT Scratched	38.00 FS	*10.00 FS
31	2		*FORK OILS	*Check	30.00 FS	*- FS
32	2		*SET FORK OIL SEALS	*Check	56.00 FS	*- FS
33	1		*SET STEERING CONE	*Check	98.00 FS	*- FS
34	1		*REAR BOX	Cut / Damaged	520.00 FS	*400.00 FS
35	1		*REAR BOX BRACKET	Bent	180.00 FS	*180.00 FS
36	1		*E.R.P IU	*Check	180.00 FS	*- FS
37	1		*SET STICKER	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,496.00	2,897.00
- List Item Discount on L Items 10.00/10.00% (\$)	527.40	218.70
Total Parts (\$)	5,968.60	2,678.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	50.00	30.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	480.00	300.00
4	TO REPAIR BODY FRAME (*Check)	New	350.00	0.00
Gross Labour Cost (\$\$)			960.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >