



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2200333  
INV Date 14/01/2022  
Reference CC4/LPC21007331/Ugs3q2  
Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SGW 2283H  
Insured Veh. GBC 1547T  
Claim No. 21/21/21/VC00/024728  
Policy No. Z/21/VC00/109641  
Accident Date 01/07/2021  
Inspection Date 16/08/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CC4/LPC21007331/Ugs3q2 Date: 14/01/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	GBC 1547T	<b>Veh. Inspected</b>	SGW 2283H
<b>Policy No.</b>	Z/21/VC00/109641	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	21/21/21/VC00/024728	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ONG LI LI	<b>Assign Date</b>	05/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	TOYOTA ESTIMA (A)	<b>c.c</b>	2362
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2007
<b>Chassis No.</b>	ACR500035240	<b>Colour</b>	SILVER
<b>Odometer</b>	281702 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/55 R17	MICHELIN	5 mm
<b>L/H Front Tyre</b>	225/55 R17	MICHELIN	5 mm
<b>R/H Rear Tyre</b>	225/55 R17	MICHELIN	5 mm
<b>L/H Rear Tyre</b>	225/55 R17	MICHELIN	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	01/07/2021	<b>Inspection Date</b>	16/08/2021
<b>Survey held at</b>	PROFI AUTOMOTIVE BLK 10 KAKI BUKIT ROAD 2 #01-05 FIRST EAST CENTRE SINGAPORE 417868		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 2283H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DENTED	1,317.80	845.10
1	FRONT BUMPER TOP BEAM	NOT NECESSARY	289.60	-
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	118.40	-
1	FRONT BUMPER REINFORCEMENT	DENTED	381.45	381.45
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	381.80	-
2	FRONT HEAD LAMP @\$1339.40	O/S CRACKED	2,798.80	1,339.40
2	FRONT BUMPER FOG LAMP COVER @\$114.90	NOT NECESSARY	229.80	-
2	FRONT BUMPER FOG LAMP @\$287.40	NOT NECESSARY	574.80	-
1	FRONT GRILLE	NOT NECESSARY	481.80	-
1	FRONT GRILLE CHROME MOULDING ASSEMBLY	SCRATCHED	361.40	361.40
1	FRONT BUMPER SPONGE	NOT NECESSARY	128.00	-
1	FRONT TOWING COVER	NOT NECESSARY	55.00	-
1	FRONT BONNET (NPA)	NOT NECESSARY	-	-
	LESS 25% DISCOUNT		-1,779.66	-731.84
			5,338.99	2,195.51
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	40.00
1	SET FRONT NUMBER PLATE AND HOLDER (SN)	NOT NECESSARY	80.00	-
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT SENSOR (SN)	NOT NECESSARY	400.00	-
			550.00	70.00
<b><u>LABOUR</u></b>				
	CHECK WIRING AND LIGHTING SYSTEM.		100.00	20.00
	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS .		600.00	300.00
	SPRAY PAINTING ON AFFECTED AREAS .		800.00	300.00
	APPLY ANTI RUST ON AFFECTED PARTS.	NOT NECESSARY	150.00	-
			1,650.00	620.00
<b>GRAND TOTAL</b>			<b>7,538.99</b>	<b>2,885.51</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,300.00</b>
---	--	--	-----------------

Report Ref No. CC4/LPC21007331/Ugs3q2

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SGW 2283H

## INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SGW 2283H**

**RE-INSPECTION**

