

# profi automotive

10 Kaki Bukit Road 2 #01-05 First East Centre S417868 M:94335558 E: profi.automotive@asia.com

16 August 2021

Date Of Accident: 01 July 2021  
 Name Of Registered Owner: Soh Chin Huat  
 Vehicle Registered Number: SGW2283H  
 Vehicle Model: Toyota Estima

Description (Listed Item)	Qty	Unit Price (\$\$)	Amount (\$\$)
Front bumper <i>TD</i> <i>845110</i>	1	<del>1317.80</del>	<del>1317.80</del>
Front bumper top beam <i>11</i>	1	289.60	289.60 X
Front bumper side retainer <i>11</i>	2	111.40	118.40 X
Front bumper reinforcement <i>TD</i>	1	381.45	381.45
Front bumper lower grille <i>11</i>	1	381.80	381.80 X
Front head lamp <i>0/scene</i>	2	1339.40	2798.80 IPC
Front bumper fog lamp cover <i>11</i>	2	114.90	229.80
Front bumper fog lamp <i>11</i>	2	287.40	574.80 X
Front grille <i>11</i>	1	481.80	481.80 X
Front grille chrome moulding assembly <i>SCA</i>	1	361.40	361.40
Front bumper sponge <i>11</i>	1	128.00	128.00 X
Front towing cover <i>11</i>	1	55.00	55.00 X
Front bonnet <i>11</i>	1	Repair	Repair X
Subtotal			7223.05
Less (25%)			1805.80
Total			5417.25

Description (Special Nett Item)	Qty	Unit Price (\$\$)	Amount (\$\$)
Front bumper clip <i>all</i>	1 set	40.00	40.00 ✓
Front number plate and holder <i>11</i>	1 set	80.00	80.00 X
Front grille clip <i>all</i>	1 set	30.00	30.00 ✓
Front sensor <i>11</i>	1 set	400.00	400.00 X
Total			550.00

*not authorized*  
*16/8/21*  
*2/s @ 2300*  
*take photo after repair*  
*4 days*  
*all recite*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*next page*  
 ↓

*P-2927.35*  
*252*  
*P-2195.51*  
*S.N-70*  
*L-620*  
*2885.57*  
*202*  
*2308*

# profi automotive

10 Kaki Bukit Road 2 #01-05 First East Centre S417868 M:94335558 E: profi.automotive@asia.com

Description (Labour)	Qty	Unit Price (S\$)	Amount (S\$)
Check wiring and lightning system		100.00	100.00
Panel beating and renew damage parts on affected areas		600.00	600.00
Spray painting on affected areas		800.00	800.00
Apply anti rust on effected parts		150.00	150.00
<b>Total</b>			<b>1650.00</b>

20  
300  
300  
X

Description (Cost of Repair)	Qty	Unit Price (S\$)	Amount (S\$)
Listed Items		5417.25	5417.25
Special Nett Items		550.00	550.00
Labour		1650.00	1650.00
<b>Subtotal</b>			<b>7617.25</b>