

profi automotive

10 Kaki Bukit Road 2 #01-05 First East Centre S417868 M:94335558 E: profi.automotive@asia.com

16 August 2021

Date Of Accident: 01 July 2021
 Name Of Registered Owner: Soh Chin Huat
 Vehicle Registered Number: SGW2283H
 Vehicle Model: Toyota Estima

Description (Listed Item)	Qty	Unit Price (S\$)	Amount (S\$)
Front bumper <i>DD 84510</i>	1	1327.80	1327.80
Front bumper top beam <i>11</i>	1	289.60	289.60 X
Front bumper side retainer <i>11</i>	2	111.40	118.40 X
Front bumper reinforcement <i>DD</i>	1	381.45	381.45 X
Front bumper lower grille <i>11</i>	1	381.80	381.80 X
Front head lamp <i>0/5CNA</i>	2	1339.40	2798.80 <i>1PC</i>
Front bumper fog lamp cover <i>11</i>	2	114.90	229.80 X
Front bumper fog lamp <i>11</i>	2	287.40	574.80 X
Front grille <i>11</i>	1	481.80	481.80 X
Front grille chrome moulding assembly <i>SCA</i>	1	361.40	361.40 X
Front bumper sponge <i>11</i>	1	128.00	128.00 X
Front towing cover <i>11</i>	1	55.00	55.00 X
Front bonnet <i>11</i>	1	Repair	Repair X
		Subtotal	7223.05
		Less (25%)	1805.80
		Total	5417.25

Description (Special Nett Item)	Qty	Unit Price (S\$)	Amount (S\$)
Front bumper clip <i>NEC</i>	1 set	40.00	40.00 ✓
Front number plate and holder <i>11</i>	1 set	80.00	80.00 X
Front grille clip <i>NEC</i>	1 set	30.00	30.00 ✓
Front sensor <i>11</i>	1 set	400.00	400.00 X
		Total	550.00

*Not Authorized
 Lian
 16/8/21
 L/S to 2300/
 take photo after repair
 4 days.
 All Cecilia*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*7-2927-38
 252
 7-2195-51
 S.N. 70
 L-620
 2885.57
 202
 2308*

*next page
 ↓*

