

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SLQ 8757 R
Accident Date : 25-Jan-2021

No. : 31647

Date : 29-Jan-2021

Our Ref : 021005 (III) / QUEK

PAGE : 1

NG CHENG CHENG (MS)
Singapore

Not Attached
1. B1, 11 Bp &

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS 1.6L CVT (2015) SKU1036A
=====

1 pc rear bumper		486.50	✓
1 pc n/s rear bumper side retainer		120.00	X
8 pcs rear bumper clips	@ S\$ 5.00	40.00	✓
1 pc n/s rear fender inner shield		52.80	X
4 pcs n/s rear fender inner shield clips	@ S\$ 5.00	20.00	X
1 pc n/s rear sport rim (original)		1,645.50	✓
1 pc n/s rear wheel hub		670.00	X
1 pc n/s rear wheel hub bearing			
1 pc n/s rear shock absorber		200.00	X
		3,234.80	
	Less 25% :	-808.70	
		2,426.10	
1 pc n/s rear tyre		180.00	sn X
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.		450.00	1801
To dismantle and check rear under-carriage. To replace affected portions.		180.00	X
To conduct front wheel alignment test.		80.00	601
To putty and respray on affected portions.		450.00	2201

Singapore Dollars Three Thousand Seven Hundred and Sixty Six and Cents Ten Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Total : S\$ 3,766.10
=====