

Cecilia



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SJX663S

Date of Accident : 02 July 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 03 July 2021

Estimate To Repair SMD754H - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7205703

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	rear bumper	\$ 549.00
02	8 ps	rear bumper clips @ \$3.50	\$ 28.00
03	1 pc	rear bumper centre pad	\$ 189.00
04	1 pc	rear bumper lower	\$ 179.00
05	2 ps	rear bumper reverse sensor @ \$160.00	\$ 320.00
06	2 ps	rear bumper side retainer @ \$28.00	\$ 56.00
07	2 ps	rear bumper reflector @ \$116.00	\$ 232.00
08	1 pc	rear bumper reinforcement	\$ 367.00
09	2 ps	rear bumper bracket @ \$84.00	\$ 168.00
10	3 ps	rear bumper lower bracket @ \$27.00	\$ 81.00
11	1 pc	rear bumper top bracket	\$ 25.00
12	1 pc	tailgate lid weatherstrip	\$ 115.00
13	1 pc	rear end panel	\$ 611.00
14	1 pc	rear end panel top garnish	\$ 123.00
			\$ 3,043.00
LABOUR & MISC. CHARGES			
01		Putty and spray painting of the affected portion.	\$ 500.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 650.00
03		To reinstall of rear bumper parking sensor.	\$ 50.00
04		To check electrical lighting concerned.	\$ 60.00
			\$ 1,260.00
Total			\$ 4,303.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			1385 102 7-12447 L- 970 22147 207 1771.76