

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA INSURANCE	DATE	: 5-Jul-21
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJL8807E		
MODEL	: TOYOTA COROLLA ALTIS 1.6		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 3-Jul-21
		TIME	: 19:30HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE SKIRT RH <i>torn</i>	1	\$ 680.20	\$ 680.20
2	FRONT DOOR RH <i>Distorted</i>	1	\$ 1,255.30	\$ 1,255.30
3	FRONT DOOR HINGE <i>Best</i>	2	\$ 80.00	\$ 160.00
4	FRONT DOOR CHECKER <i>New</i>	1	\$ 130.00	\$ 130.00
5	FRONT DOOR OUTER PROTECTOR <i>Distorted</i>	1	\$ 280.30	\$ 280.30
6	FRONT BUMPER <i>torn</i>	1	\$ 594.00	\$ 594.00
7	FRONT BUMPER SIDE RETAINER <i>New</i>	1	\$ 62.00	\$ 62.00
8	FRONT BUMPER LOGO <i>New</i>	1	\$ 90.00	\$ 90.00
9	FRONT HEADLAMP <i>New</i>	1	\$ 488.20	\$ 488.20
10	FRONT HEADLAMP LOWER BRACKET <i>New</i>	1	\$ 52.00	\$ 52.00
11	FRONT FENDER <i>Distorted</i>	1	\$ 422.50	\$ 422.50
12	FRONT FENDER EMBLEM "VVT-I" <i>New</i>	1	\$ 63.20	\$ 63.20
13	FRONT FENDER INNER COWLING <i>torn</i>	1	\$ 230.00	\$ 190.20
14	FRONT LOWER ARM RH <i>Best</i>	1	\$ 354.10	\$ 354.10
15	FRONT KNUCKLE ARM RH <i>New</i>	1	\$ 232.10	\$ 232.10
16	FRONT KNUCKLE ARM BEARING RH <i>Best</i>	1	\$ 187.20	\$ 187.20
17	FRONT SHOCK ABSORBER RH <i>Best</i>	1	\$ 326.50	\$ 326.50

451620

3387.15

TOTAL PRICE \$ 5,567.80
LESS 25% \$ 1,391.95

SUB TOTAL PRICE \$ 4,175.85

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SIDE SKIRT CLIPS (SET) <i>Ner</i>	1	\$ 20.00	\$ 20.00
1	FRONT BUMPER CLIPS (SET) <i>Ner</i>	1	\$ 20.00	\$ 20.00
2	HEADLAMP CLIPS <i>Ner</i>	1	\$ 20.00	\$ 20.00
3	FRONT FENDER COWLING CLIPS <i>Ner</i>	1	\$ 20.00	\$ 20.00
4	FRONT WHEEL RIM LH <i>Ct</i>	1	\$ 1,000.00	\$ 1,000.00 400
5	FRONT WHEEL TYRE LH <i>Ner</i>	1	\$ 280.00	\$ 280.00

TOTAL \$ 1,360.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	500	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	800	
3	TO REMOVE AND REFIX FRONT LH DOOR <i>Refix</i>	\$ 250.00	800 X	
4	TUFF COAT	\$ 250.00	40	
5	WIRING CHECK	\$ 250.00	30	
6	TO REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 100.00	80	
7	REFOCUS HEADLAMP BEAM	\$ 60.00	X	
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	200	
9	FOUR WHEEL ALIGNMENT	\$ 120.00	80	

TOTAL \$3,380.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,535.85
TOTAL LABOUR COST : \$ 3,380.00
TOTAL REPAIR COST : \$ 8,915.85

APPROVED DETAILS

SURVEYOR

CONTACT NO

PART BY PART / LUMP SUM

NO OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX

Adnan Ly

4/s 06/07/21.

05 Days.

Wheel: 5577.15

4/s: 441c.

460

1730