



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007351/Euf3e2	
			Date: 11/10/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 178U	Veh. Inspected	SLP 8805R
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/07/21/2003	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	06/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MHFB29F3302009857	Colour	GREY
	Odometer	313448 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	WEST LAKE	5 mm
	L/H Front Tyre	195/50 R16	WEST LAKE	5 mm
	R/H Rear Tyre	195/50 R16	WEST LAKE	5 mm
	L/H Rear Tyre	195/50 R16	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/07/2021	Inspection Date	06/07/2021
	Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	