



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

|   |                   |   |           |  |                   |
|---|-------------------|---|-----------|--|-------------------|
| <b>LONPAC INSURANCE BHD</b><br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSE<br>SINGAPORE 199555<br><b>ATTN. :</b> MOTOR CLAIMS<br><b>FAX :</b> |                   | <b>NAME :</b><br><b>ADDRESS :</b><br><b>TEL :</b> |           | <b>WIP :</b> 37225<br><b>EXCESS :</b><br><b>DATE:</b> 6-Jul-21 |                   |
| <b>VEH NO :</b>   | <b>SMN2119B</b>   | <b>DATE IN :</b>                                  |           | <b>CONTACT PERSON :</b>  | JESS              |
| <b>CHASSIS NO :</b>   | JM6GL1072K0313005 | <b>MILEAGE :</b>                                  |           | <b>TYPE OF CLAIM :</b>   | THIRD PARTY CLAIM |
| <b>MODEL :</b>  | M6                | <b>DATE REG:</b>                                  | 29-Jul-19 | <b>POLICY NO. :</b>  |                   |

**NATURE OF WORKS**

**Parts Description**

| NO               | DESCRIPTION                      | PARTS NO        | QTY | /UNIT    | DISC | 1st | Supp | REVISED | PRICES   |
|------------------|----------------------------------|-----------------|-----|----------|------|-----|------|---------|----------|
| 1                | HEADLAMP RH                      | MGSK4-51-031A   | 1   | 4,759.30 | 20%  |     |      |         | 4,759.30 |
| 2                | TAPE SEAL HEADLAMP RH            | MGRF5-51-065A   | 1   | 102.00   | 20%  |     |      |         | 102.00   |
| 3                | RIVET                            | MB092-51-833    | 1   | 3.50     | 20%  |     |      |         | 3.50     |
| 4                | BRACKET 'A' HEADLAMP RH          | MGSH7-50-ABXA   | 1   | 30.80    | 20%  |     |      |         | 30.80    |
| 5                | BRACKET 'B' HEADLAMP RH          | MGSH7-50-ABYA   | 1   | 15.50    | 20%  |     |      |         | 15.50    |
| 6                | SIDE MIRROR RH                   | MGSB9-69-121A   | 1   | 475.90   | 20%  |     |      |         | 475.90   |
| 7                | HOUSING SDIE MIRROR RH           | MB63B-69-1N1 13 | 1   | 111.00   | 20%  |     |      |         | 111.00   |
| 8                | SIGNAL TURN LAMP RH              | MB63B-69-122A   | 1   | 85.80    | 20%  |     |      |         | 85.80    |
| 9                | GLASS & HOLDER RH                | MB63C-69-1G1    | 1   | 282.50   | 20%  |     |      |         | 282.50   |
| 10               | FRONT FENDER RH                  | MGHP9-52-111A   | 1   | 383.70   | 20%  |     |      |         | 383.70   |
| 11               | FASTENER                         | MB45A-56-146A   | 10  | 3.00     | 20%  |     |      |         | 30.00    |
| 12               | FRT BUMPER                       | MGJ8-50-031 BB  | 1   | 1,211.90 | 20%  |     |      |         | 1,211.90 |
| 13               | GROMMET,SCREW                    | MGHP9-50-0Z5    | 1   | 2.90     | 20%  |     |      |         | 2.90     |
| 14               | CHROME COVER FOG LAMP            | MGBVG-50-121    | 1   | 65.80    | 20%  |     |      |         | 65.80    |
| 15               | COVER FOG LAMP                   | MGSH7-50-101    | 1   | 20.50    | 20%  |     |      |         | 20.50    |
| 16               | RETAINER RH FORNT BUMPER         | MGHP9-50-0T1B   | 1   | 17.10    | 20%  |     |      |         | 17.10    |
| 17               | RIVET                            | MBBM4-50-355    | 4   | 4.50     | 20%  |     |      |         | 18.00    |
| 18               | RIVET,SPLASH SHIELD              | MS51S-51-833    | 4   | 4.00     | 20%  |     |      |         | 16.00    |
| 19               | CHROME MOULD OUTER FRONT DDOR RH | MGHP9-50-640F   | 1   | 96.00    | 20%  |     |      |         | 96.00    |
| 20               | FASTENER                         | MGJ6A-68-AB1    | 9   | 7.20     | 20%  |     |      |         | 64.80    |
| TOTAL PARTS      |                                  |                 |     |          |      |     |      |         | 7,793.00 |
| LESS 20%         |                                  |                 |     |          |      |     |      |         | 1,558.60 |
| TOTAL PARTS COST |                                  |                 |     |          |      |     |      |         | 6,234.40 |

**SUPPLEMENTARY**

| NO               | DESCRIPTION | PARTS NO | QTY |  |  | 1st | Supp | REVISED | PRICES |
|------------------|-------------|----------|-----|--|--|-----|------|---------|--------|
| 1                |             |          |     |  |  |     |      |         |        |
| 2                |             |          |     |  |  |     |      |         |        |
| 3                |             |          |     |  |  |     |      |         |        |
| TOTAL PARTS      |             |          |     |  |  |     |      |         | -      |
| TOTAL PARTS COST |             |          |     |  |  |     |      |         | -      |

| Labour Description               |              |  |                    |             |
|----------------------------------|--------------|--|--------------------|-------------|
|                                  |              |  |                    |             |
| 1                                |              | TO REPLACE FRONT BUMPER AND FRONT FENDER RH . TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.   |                    | 1,650.00    |
| 2                                |              | TO RESPRAY FRONT BUMPER,FRONT FENDER RH,FRONT DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENTS. |                    | 2,520.00    |
| 3                                | MZ-BR-FRTSEN | TO TRANSFER FRONT PEDESTRIAN SENSORS.  | NETT               | 330.00      |
| 4                                | MZ-BR-ELECTR | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.   | NETT               | 150.00      |
| 5                                | MZ-BR-REPROG | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.  | NETT               | 180.00      |
| 6                                | MZ-BR-SUNDR  | SUNDRIES.  |                    | 50.00       |
|                                  |              |  | TOTAL LABOUR       | - 4,880.00  |
|                                  |              |  | TOTAL PARTS        | - 6,234.40  |
|                                  |              |  | TOTAL              | - 11,114.40 |
|                                  |              |  | LESS EXCESS        | - -         |
|                                  |              |  | TOTAL AFTER EXCESS | - -         |
|                                  |              |  | GST 7%             | - -         |
|                                  |              |  | GRAND TOTAL        | - -         |
| SUPPLEMENTARY LABOUR DESCRIPTION |              |  |                    |             |
|                                  |              |  |                    |             |
| 1                                |              | #N/A   |                    |             |
| 2                                |              | #N/A   |                    |             |
|                                  |              |  | TOTAL LABOUR       | - -         |
|                                  |              |  | TOTAL PARTS        | - -         |
|                                  |              |  | TOTAL              | - -         |
|                                  |              |  | LESS EXCESS        | - -         |
|                                  |              |  | TOTAL AFTER EXCESS | - -         |
|                                  |              |  | GST 7%             | - -         |
|                                  |              |  | GRAND TOTAL        | - -         |

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**RANS EUROKARS PTE LT**

\_\_\_\_\_  
Authorised Signature