

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) ___ S + RS ___ SI

) Photos

) Others

TOTAL

11/10/21 4/5 @ 3700 confirmed with Alar.

per 8th.
 Coe until 31-10-2025 H1A8 10989
 please check liability urgent

have G.A

Vehicle: IN / OUT

B-276K

\$35k.

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

6

mm

6

mm

6/7/21

Rear

6/6

mm

6/6

mm

D.O.I.

6/7/21

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

not full bond
held
6/7/21
4s \$3700
3 days.

VEHICLE No: PC 8232P

1PC	FRONT BUMPER ASSY	deep cut / cut	2850	\$4,800.00 ✓
1PC	FRONT BODY PANEL O/S	R		\$6,900.00 X
1PC	HEADLAMP O/S	11		\$1,550.00 X
1PC	FRONT SIDE PANEL O/S	R	(10%)	\$1,280.00 X
				\$14,530.00

TO CHECK WIRING
LABOUR FOR PANEL BEATING, REPLACED PARTS
TO PUTTY & SPRAY PAINTING
TO RESET & REPROGRAMME SYSTEM

\$50.00 20
\$1,800.00 / 200
\$1,500.00 850
11 \$250.00 X
TOTAL \$18,130.00

p - 2850
10%
p - 2855
2 - 2070
4635
207
3708

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: