



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007374/Euf3n2	
			Date: 02/08/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 621C	Veh. Inspected	SLQ 5107L
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/21/2066	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	06/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	mitsubishi attrage	c.c	1193
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MMBSTA13AHH006040	Colour	BLUE
	Odometer	54124 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	YOKOHAMA	4 mm
	L/H Front Tyre	185/55 R15	YOKOHAMA	4 mm
	R/H Rear Tyre	185/55 R15	YOKOHAMA	4 mm
	L/H Rear Tyre	185/55 R15	YOKOHAMA	4 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/07/2021	Inspection Date	21/07/2021
	Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	