

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB9926P

AAD2107-002

Not Authorised

Recovery By paint

2027.43

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

05 JUL 2021

SHB9926P

JTDKB3FU903091430

TOYOTA

PRIUS GEN 4

30/06/2021

Tokio

31/08/2020

		PART	LIST	
1	HOOD SUB-ASSY		<i>Am</i>	983.1 ✓
1	COVER, FRONT BUMPER		<i>Am/Lm</i>	521.00 ✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER		<i>R</i>	716.60 X
1	REINFORCEMENT, FRONT BUMPER, NO.2		<i>R</i>	246.10 X
1	ABSORBER, FRONT BUMPER, LOWER		<i>Sm</i>	132.70 X
1	ABSORBER, FRONT BUMPER ENERGY		<i>Sm</i>	80.20 X
1	SUPPORT, FRONT BUMPER SIDE, LH		<i>Sm</i>	82.30 X
1	STAY SUB-ASSY, FRONT BUMPER, RH		<i>Sm</i>	47.50 X
1	BRACKET, FRONT BUMPER SIDE, LH		<i>Sm</i>	59.30 X
1	BRACKET, FRONT BUMPER SIDE, RH		<i>Sm</i>	59.30 X
1	UNIT ASSY, HEADLAMP, LH		<i>Sm</i>	2,637.60 X
1	UNIT ASSY, HEADLAMP, RH		<i>Sm</i>	2,637.60 X
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1		<i>Sm</i>	3,772.50 X
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1		<i>Sm</i>	3,772.50 X
1	GRILLE SUB-ASSY, RADIATOR		<i>Sm</i>	422.50 X
1	GRILLE, RADIATOR, LOWER NO.1		<i>Sm</i>	178.60 X
1	EMBLEM ASSY, RADIATOR GRILLE		<i>Am/Lm</i>	105.80 X
TOTAL			\$	15,472.10
25%			\$	3,868.03
			\$	11,604.08

Special Nett

FRONT NUMBER PLATE WITH HOLDER	\$	<i>Sm</i>	140.00 X
FRONT BUMPER CLIP FRT	\$	<i>Mc</i>	95.00 <i>50Sm</i>
FRONT BUMPER RETAINER CLIP	\$	<i>an</i>	85.00 X
TOTAL	\$		320.00

TOTAL PARTS \$ 11,924.08

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9926P**AAD2107-002****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	300/
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	30/
Towing Fees	\$	nn	150.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9926P

AAD2107-002

Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	440/
To reinstall rear bumper parking sensor.	\$	~ 170.00	X
To Check Electrical Lighting Concerned.	\$	~ 170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 220.00	X
To replace, refill and top up coolant for radiator	\$	~ 170.00	X
To lift-up / out engine with gear box and refit.	\$	~ 440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	~ 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	~ 380.00	X
TOTAL	\$	10,290.00	

Over All Total \$ 22,214.08

(PART-BY-PART) Repair Days

25 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: