



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21007379/Evf3e2	
			Date: 04/08/2021	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SDY 9282P	Veh. Inspected	SBP 170J
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D13312107	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	06/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	VOLKSWAGEN TOURAN	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WVGZZZ1TZKW072718	Colour	BEIGE
	Odometer	21846 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	PIRELLI	5 mm
	L/H Front Tyre	215/55 R17	PIRELLI	5 mm
	R/H Rear Tyre	215/55 R17	PIRELLI	5 mm
	L/H Rear Tyre	215/55 R17	PIRELLI	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/07/2021	Inspection Date	08/07/2021
	Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	