

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

5-Jul-21

Our ref : TP/5004/21

Tan Buck Kiang

TP Chinn.
Asher.

MP053REH104561455

RE : estimate cost for vehicle no : SLL 6295X

1 pc	bonnet <i>Dented</i>	\$	1,037.30 ✓	
1 pc	bonnet lock <i>ren</i>		130.00 ✗	
1 pc	bonnet rubber <i>ren</i>		60.00 ✗	
2 pcs	bonnet hinges <i>ren</i>		150.00 ✗	
1 pc	frt grille <i>crushed</i>		564.00 ✓	389
1 pc	frt grille logo <i>ren</i>		45.90 ✓	
6 pcs	frt grille clips <i>ren</i>		30.00 ✓	
2 pcs	headlamp w/chrome <i>crushed</i>		5,690.60 ✓	5136
1 pc	frt grille top garnish <i>Dented</i>		112.05 ✓	
1 pc	air con condenser <i>Dented</i>		1,507.40 ✓	1289
1 pc	radiator <i>clean</i>		1,782.20 ✗	
1 pc	frt brace panel <i>Best</i>		155.00 ✓	
1 pc	frt support panel <i>per</i>		889.50 ✗	
1 pc	frt bumper <i>Dented</i>		558.10 ✓	
1 pc	frt bumper sponge <i>ren</i>		78.80 ✗	
			12,790.85	
less 25%			3,197.71	
			9,593.14	
1 pc	frt no plate ren not nec		40.00 snett ✗	
Panel beating.			1,000.00 400	
Spray painting.			1,000.00 600	
Wiring.			30.00 ✓	
Top up gas.			120.00 80	
			11,783.14	
Plus 7% GST			824.82	
			12,607.96	

SD : twelve thousand six hundred seven & cents ninety-six only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lin

1/5 05/07/21

05 days

total: 7721.76

1/5: 6150