

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0557/2021/ZK
DATE : 6-Jul-21
WIP : 34234

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 8/7/2021

YOUR INSURED VEH NO :SMN 1346 T

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM ZHIHAO, SHAUN
ADDRESS : 13 YISHUN STREET 51 THE CRITERION
#09-26
SINGAPORE 767972
TELEPHONE : HP +65 97552220
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5078830042-05
VEHICLE NO : **SKE 900 X**
MODEL CODE : A3 SPORTSBACK 1.4 TFSI
MODEL YEAR : 30/4/2015
ENGINE NO : CZC 248570
CHASSIS NO : WAUZZZ8V4FA143776
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Jul-21
PLACE OF ACCIDENT : ROAD SIDE PARKING OUTSIDE 182 TAI KENG GARDENS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 900 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID, CHECK FUNCTION.	S/N \$ 280.00 ✓	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 500 ✓	✓
3	TO RESPRAY BUMPER	\$ 900.00 550 ✓	✓
4	TO CARRY OUT DIAGNOSTIC CHECK	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 2,422.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 900 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Dehnd</i>	1	\$ 2,070.00 ✓	1,656.00
2	REAR BUMPER FIXING PARTS <i>Me n</i>	1	\$ 193.00 ✗	
3	REAR BUMPER LOCKING MECHANISM - LH / RH <i>Me n</i>	2	\$ 28.00 ✗	
4	REAR BUMPER SPOILER <i>Me n</i>	1	\$ 237.00 ✗	
5	REAR BUMPER REINFORCEMENT BEAM <i>Me n</i>	1	\$ 603.00 ✗	
6	REAR BUMPER BRACKET LH / RH <i>Me n</i>	2	\$ 26.00 ✗	
7	REAR PARKING AID SENSOR <i>Me n</i>	2	TBC	+
8	REAR PARKING AID SENSOR SEAL RING <i>Me n</i>	4	\$ 14.00 ✗	
9	EXHAUST TRIM <i>Me n</i>	1	TBC	✗
10	SUNDRIES ?	S/N	\$ 300.00	X
TOTAL SPARE PARTS		:	\$ 3,471.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 5,893.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L.*
SURVEYED DATE : *08/07/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT