

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007389/T1GA3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100455295
Claimant Vehicle No :	SMJ1422C	Insured Vehicle No :	SLA6291P
Date of Loss:	05/07/2021	Nature of Claim:	TP
		Claim No:	8997743772SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ1422C	Engine No:	G4FGKU094990
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMKU866441
Reg. Date:	25/02/2019 (Man. Year: 2019)	Odometer:	15508 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,163.60	1,041.52	1,122.08	51.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	830.00	1,550.00	65.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,543.60	1,871.52	2,672.08	58.81
+ GST 7.00/7.00% (S\$)	318.05	131.01	187.04	58.81

Nett Amount (S\$)	4,861.65	2,002.53	2,859.12	58.81
		+ Loss of Use (4.0 x S\$50.00/day) (S\$)	200.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	2,204.53	
		Global Sum Settlement (S\$)	2,200.00	

INSPECTION

Date of Assignment: 06/07/2021

Date Inspected: 06/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 F	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 F	*- FL
3	1		*REAR BUMPER N/S SIDE BRACKET	Not Necessary	29.10 F	*- FL
4	1		*REAR BUMPER N/S STAY	Not Necessary	78.40 F	*- FL
5	1		*REAR BUMPER LOWER COVER	Cracked	353.50 F	*353.50 FL
6	1		*REAR BUMPER N/S REFLECTOR	Cracked	201.50 F	*201.50 FL
7	1		*LH TAIL LAMP	Not Necessary	330.00 F	*- FL
8	1		*REAR N/S AIR EXTRACTOR	Not Necessary	38.90 F	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
10	1		*SET REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
11	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,163.60	1,244.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	202.88
Total Parts (\$\$)	2,163.60	1,041.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE END PANEL ,REAR N/S FENDER ETC	New	1,000.00	400.00
4	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,REAR BUMPER ,LOWER COVER ,END PANEL,REAR N/S FENDER	New	1,000.00	400.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	0.00
Gross Labour Cost (S\$)			2,380.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >