

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

6-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SMJ 1422 C

1 pc	Rear bumper	ana	\$	-	459.40
1 pc	Rear bumper reinforcement	X ny	\$	-	294.80
1 pc	Rear bumper n/s side bracket	X ny	\$	-	29.10
1 pc	Rear bumper n/s stay	X ny	\$	-	78.40
1 pc	Rear bumper lower cover	ana	\$	-	353.50
1 pc	Rear bumper n/s reflector	ana	\$	-	201.50
1 pc	LH tail lamp	X ny	\$	-	330
1 pc	Rear n/s air extractor	X ny	\$	-	38.90
				\$	-
				\$	-
					1014.40
					20% - 811.52

Less 20%

S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor

Sundry

To check wiring

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, rear n/s fender etc

To putty and spray painting on the rear bumper, rear bumper lower cover, end panel, rear n/s fender

To apply rustproofing on the repaired and replaced panels.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	48.00	3000
\$	280.00	2000
		230.
\$	50.00	X ny
\$	50.00	30
\$	180.00	X ny
\$	1,000.00	200 400.
\$	1,000.00	200 400.
\$	150.00	X ny 830

811.52

230

830

\$1871.52, 3days

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

Taufik 97415749
wp 6/7/21 05pm 03days
P/p Resurvey before permit