



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2207622

INV Date 09/12/2022

Reference CC4/LPC21007404/Kpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 3483X
Insured Veh. GN 1878X
Claim No. 21/21/21/VC05/024737
Policy No. Z/21/VC00/109599
Accident Date 05/07/2021
Inspection Date 08/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21007404/Kpa3q2 Date: 09/12/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GN 1878X	Veh. Inspected	SLF 3483X	
Policy No.	Z/21/VC00/109599	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/024737	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	07/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 318I (A)	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA8E320X0K497904	Colour	METALLIC GREY	
Odometer	85424 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	PIRELLI	7 mm	
L/H Front Tyre	225/55 R16	PIRELLI	7 mm	
R/H Rear Tyre	225/55 R16	PIRELLI	7 mm	
L/H Rear Tyre	225/55 R16	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2021	Inspection Date	08/07/2021	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 3483X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT / CRACKED	1,184.75	1,184.75
1	REAR BUMPER REINFORCEMENT	BENT	470.25	470.25
1	REAR BOOT	BUCKLED	1,241.10	1,241.10
1	REAR BOOT LH REFLECTOR	CUT	322.80	322.80
1	REAR BOOT EMBLEM	NECESSARY	64.75	64.75
1	REAR BOOT INNER RUBBER	SERVICEABLE	126.80	-
1	TAILLAMP LH	CRACKED	546.55	546.55
1	LH REVERSE SENSOR	SCRATCHED	239.25	239.25
	LESS 5% DISCOUNT		-209.81	-203.47
			3,986.44	3,865.98
	<u>LABOUR</u>			
	REMOVE & REFIT REAR BUMPER ASSY ,TAILLAMPS, REAR BOOT AND ATTACHMENTS ,LOCK ASSY.TO KNOCK ,REPAIR REAR PANEL AND REALIGN THE SAME.		700.00	500.00
	PUTTY AND RESPRAY ON REAR PANEL,BOOT ,REAR BUMPER .		700.00	600.00
	REMOVE AND REFIT REVERSE CAMERA ,SENSOR ASSY AND CHECK SYSTEM.		60.00	60.00
	RUSTPROOFING.		30.00	30.00
			1,490.00	1,190.00
	GRAND TOTAL		5,476.44	5,055.98
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CC4/LPC21007404/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 3483X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 3483X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 3483X

RE-INSPECTION

