

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLF3483X
TP/wnpac

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62963767

ATTN: Motor Claim Department *Not in hand*

WS Ref: TP/LONPAC *6/1 Rmp B*
Claim Type: Third Party *Return After Paint*
Accident Date: 05/07/2021
TP Veh Reg No: GN1878X *4 days*

Estimate No: ES2190642/WS
Date: 08 Jul 2021
Policy No: 5118685747
Veh Reg No: SLF3483X
Make/Model: BMW BMW 318I SEDAN LED
Chassis No: WBA8E320X0K497904
Engine No: F6511303B38B15A
Reg. Date: 25/02/2016

Estimate Repair Cost to Vehicle No :SLF3483X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	1,184.75	1 PC	<i>ATLUNA</i> 1,184.75	✓
2 REAR BUMPER REINFORCEMENT	470.25	1 PC	470.25	?
3 REAR BOOT	1,241.10	1 PC	<i>Am</i> 1,241.10	✓
4 REAR BOOT LH REFLECTOR	322.80	1 PC	<i>CA</i> 322.80	✓
5 REAR BOOT EMBLEM	64.75	1 PC	<i>MA</i> 64.75	✓
6 REAR BOOT INNER RUBBER	126.80	1 PC	126.80	?
7 TAILLAMP LH	546.55	1 PC	<i>CMA</i> 546.55	✓
8 LH REVERSE SENSOR	239.25	1 PC	<i>SEN</i> 239.25	✓
			4,196.25	
		Less 5%	209.81	3,986.44
Labour				
9 REMOVE & REFIT REAR BUMPER ASSY, TAILLAMPS, REAR BOOT AND ATTACMENTS, LOCK ASSY. TO KNOCK, REPAIR REAR PANEL AND REALIGN THE SAME.	700.00	1 LA	700.00	<i>500</i>
10 PUTTY AND RESPRAY ON REAR PANEL, BOOT, REAR BUMPER.	700.00	1 LA	700.00	<i>600</i>
11 REMOVE AND REFIT REVERSE CAMERA , SENSOR ASSY AND CHECK SYSTEM.	60.00	1 LA	60.00	✓
12 RUSTPROOFING.	30.00	1 LA	30.00	✓
			1,490.00	1,490.00
Total				S\$ 5,476.44
Add GST @ 7%				383.35
Total Amount Payable				<u>S\$ 5,859.79</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE