

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

CS/SG/21007410/UT#3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMN1784L*

at Workshop m/s *Imperium*

of _____

Insured: *SLU 317J*

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *\$53k.*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1196

Vehicle: IN / OUT

Date: _____ Person Contacted: *29/5/13*

Veh No: *SMN1784L* Yr Regn: *20/13/14*

Type: McCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CAI*

Make: *mer Benz CLA220 c.c 2143*

Colour *purple* A/C: Insured / Std / NI / NA

Sp. Reading *98544* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WDD1173032N020618*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Burn / STD A/Rim or

Tyre Size: F: _____

R: *225/40 R18 16k2*

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *4/7/21*

D.O.I. *7/7/21*

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/5/13 34981

9/7/21 4/583100 confirmed with Shawn

red: 4731.78;60%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *3*

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

___ \$ + RS. ___ \$

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$) _____)

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800
Tel: 9748 9940 Fax: 6346 7213

Vehicle No.: SMN 1784L

Model: Mercedes CLA220

QTY

List Price:

1	Front Fender - L	20/300+	1918.45
1	Front Door - L	11	
2	Front Door Hinge - L @ 112.00	11	
1	Front Door Checker - L	11	
1	Front Door Inner Rubber - L	11	301.22
1	Front Door Glass Moulding - L	11	
1	Front Door Mirror Assy - L	shorted/damaged	1045.81
1	Rocket Panel Garnish - L	11	
1	Rocket Panel Garnish Clips - L	11	

Less 10%

Prices \$
1021.25 X
2018.42
224.00 X
161.00 X
305.97
168.35 X
1367.32
820.11 X
60.00 X
6146.42
-614.64
Subtotal 5531.78

Labour Charges:

Panel Beating
To respray painting on affected areas
Wiring Check
Diagnostic Check & Clearing Off Fault Code

1000.00	420
1000.00	500
100.00	20
11	200.00 X
Subtotal	2300.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 7831.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
Sale
7/7/21
2/s \$ 3100
3 days
whenever after up.

p. 3268.48
10%
p. 2938.93
L- 940
3878.93