

# EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: 199804930G



## \*\*\* PROFORMA INVOICE \*\*\*

## TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Mr Lam Hin Yui Matthew  
Matthew Lam Hin Yui  
1091 Serangoon Road  
#04-05  
Singapore 328190

China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
079909  
Invoice to: 100090

### Document No.:

Document Date: 11/4/2022  
REGN No.: SNA989B  
Odometer: 21469  
Model: 2016 Huracan  
Variant: LP580-2  
Vehicle ID No.: ZHWEC2ZF9GLA04857  
Repair Order No.: 19116  
Delivery Date: 03/05/2017  
Page: 1 of 2  
Advisor: Ng Jiong How

### 3RD PARTY INSURANCE CLAIM AGAINST CHINA TAIPING INSURED, SBJ333M.

\*Vehicle received on 5th July 2021.

Insurer: Allianz Insurance

Policy number: SP2000015769-01

Policy holder: Mr. Matthew Lam Hin Yui

DOA: 3th July 2021

Location of accident: Intersection of Orchard road & Bideford road.

Surveyor: LKK Auto Consultants (Mr. Rasul & Mr. Steve)

LOU: To claim 8 days at \$200 per day.

Labour to dismantle and reinstall new panels.

\$4,800.00

-To replace LH door, LH side skirt.

Cost to respray new panels.

\$4,000.00

-To spray new LH door, LH side skirt.

To replace & spray rear fender left

\$4,000.00

-Interior panels and rear bumper removed for Fender replacement.

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
4T8831051E	DOOR SHELL LH LP580	36,180.00	32,562.00	1.00	32562.00
4T8809601E	REAR FENDER LH LP610	20,505.00	18,454.50	1.00	18454.50
4T0853921A	SIDE MEMBER ARM FRT	30.00	27.00	1.00	27.00
4T0853231A	SIDE MEMBER ARM	52.88	47.59	1.00	47.59
4T0837911C	DOOR SEAL LH LP580	549.00	494.10	1.00	494.10
WHT003237	DOOR CATCH SCREW LP580	2.35	2.12	10.00	21.20
N91203201	DOOR REINFORCEMENT SCREW	4.05	3.65	5.00	18.25
N91084201	12 SOCKET HEAD BOLT	5.68	5.11	5.00	25.55
N90821401	EXPANSION NUT	2.45	2.21	10.00	22.10
N90777702	SNAP NUT CLAMP	2.05	1.85	10.00	18.50
8S0837249	DOOR ARRESTER	63.45	57.11	1.00	57.11

Continued Next Page ...

**EUROSPORTS AUTO PTE LTD**

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: 199804930G



**\*\*\* PROFORMA INVOICE \*\*\***

Deliver To: Mr Lam Hin Yui Matthew  
Matthew Lam Hin Yui  
1091 Serangoon Road  
#04-05  
Singapore 328190

China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
079909  
Invoice to: 100090

# TAX INVOICE

**GST Reg No.: M90368995L**

## Document No.:

Document Date: 11/4/2022  
REGN No.: SNA989B  
Odometer: 21469  
Model: 2016 Huracan  
Variant: LP580-2  
Vehicle ID No.: ZHWEC2ZF9GLA04857  
Repair Order No.: 19116  
Delivery Date: 03/05/2017  
Page: 2 of 2  
Advisor: Ng Jiong How

**3RD PARTY INSURANCE CLAIM AGAINST CHINA TAIPING INSURED, SBJ333M.**

4T0853373C	SCUFF PLATE LH LP610	385.00	320.04	1.00	320.04
8H0831701	SCREW	3.88	3.49	5.00	17.45
8H0806221	COMPENSATING PIECE LP700	14.25	12.83	2.00	25.66
4T0898307	SIDE SKIRT LH LP610	3,255.00	2,929.50	1.00	2929.50
4T0831431	DOOR REINFORCEMENT RUBBER LP580	21.15	19.04	1.00	19.04
					<b>\$55,059.59</b>

**To installed Sticker wrap on new panels after Accident repair.**

- Installed Matte Black sticker wrap on new panels.

**\$2,500.00**

-LH door, LH side skirt, LH side mirror and LH rear fender.

EuroSports Auto Pte Ltd

**Sub Total for All: \$70,359.59**

**Rounding:** \$0.00

**GST:** \$4,925.17

**Total:** \$75,284.76

Signature

Date \_\_\_\_\_

**Terms:**

Any objections to the validity of the charges must be made within seven (7) days from the date of this Invoice otherwise it is assumed this Bill is accepted as correct.

**GOODS SOLD ARE NOT RETURNABLE OR REFUNDABLE**