

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: 199804930G



*** PROFORMA INVOICE ***

TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Mr Lam Hin Yui Matthew
Matthew Lam Hin Yui
1091 Serangoon Road
#04-05
Singapore 328190

Cash Workshop Sales

Invoice to: 99999

Document No.:

Document Date: 13/4/2022
REGN No.: SNA989B
Odometer: 21469
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF9GLA04857
Repair Order No.: 19116
Delivery Date: 03/05/2017
Page: 1 of 2
Advisor: Ng Jiong How

3RD PARTY INSURANCE CLAIM AGAINST CHINA TAIPING INSURED, SBJ333M.

*Vehicle received on 5th July 2021.

Insurer: Allianz Insurance

Policy number: SP2000015769-01

Policy holder: Mr. Matthew Lam Hin Yui

DOA: 3th July 2021

Location of accident: Intersection of Orchard road & Bideford road.

Surveyor: LKK Auto Consultants (Mr. Rasul & Mr. Steve)

LOU: To claim 8 days at \$200 per day.

Labour to dismantle and reinstall new panels.

\$4,800.00

-To replace LH door, LH side skirt.

Cost to respray new panels.

\$4,000.00

-To spray new LH door, LH side skirt.

To replace & spray rear fender left

\$4,000.00

-Interior panels and rear bumper removed for Fender replacement.

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
4T8831051E	DOOR SHELL LH LP580	36,180.00	32,562.00	1.00	32562.00
4T8809601E	REAR FENDER LH LP610	20,505.00	18,454.50	1.00	18454.50
4T0853921A	SIDE MEMBER ARM FRT	30.00	27.00	1.00	27.00
4T0853231A	SIDE MEMBER ARM	52.88	47.59	1.00	47.59
4T0837911C	DOOR SEAL LH LP580	549.00	494.10	1.00	494.10
WHT003237	DOOR CATCH SCREW LP580	2.35	2.12	10.00	21.20
N91203201	DOOR REINFORCEMENT SCREW	4.05	3.65	5.00	18.25
N91084201	12 SOCKET HEAD BOLT	5.68	5.11	5.00	25.55
N90821401	EXPANSION NUT	2.45	2.21	10.00	22.10
N90777702	SNAP NUT CLAMP	2.05	1.85	10.00	18.50
8S0837249	DOOR ARRESTER	63.45	57.11	1.00	57.11

Continued Next Page ...

REG. NO.: 199804930G

