



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6738D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FACE-FRONT	CUT	594.00	594.00
1	ENERGY ABSORBER-FRONT BUMPER	NOT NECESSARY	126.00	-
1	BRACKET-FRONT BUMPER CORNER,RIGHT	NOT NECESSARY	36.00	-
1	BRACKET-FRONT BUMPER CORNER,LEFT	NOT NECESSARY	36.00	-
1	BRACKET-FRONT BUMPER SIDE,RIGHT	NOT NECESSARY	12.60	-
1	BRACKET-FRONT BUMPER SIDE,LEFT	NOT NECESSARY	12.60	-
1	MOLDING-FRONT BUMPER LEFT	NOT NECESSARY	43.20	-
1	BACK BEAM COMPLETE-FRONT	NOT NECESSARY	288.00	-
1	COVER-FRONT BUMPER	NOT NECESSARY	4.40	-
1	PACKING-BUMPER,RIGHT	NOT NECESSARY	9.00	-
1	PACKING-BUMPER,LEFT	NOT NECESSARY	9.00	-
1	PANEL COMPLETE-RADIATOR	NOT NECESSARY	360.00	-
1	BRACKET-FOG LIGHT FRONT LEFT	NOT NECESSARY	19.80	-
	LESS 20% DISCOUNT		-	-118.80
			1,550.60	475.20
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	FRONT NUMBER PLATE (SN)(ADDITIONAL)	NECESSARY	45.00	45.00
			145.00	45.00
	<u>LABOUR</u>			
	REPAIR/REPLACE FRONT BUMPER & BEAM.		2,240.00	560.00
	RESPRAY FRONT BUMPER & BEAM.		1,680.00	420.00
	WHEEL ALIGNMENT.	NOT NECESSARY	171.00	-
	FAULT DIAGNOSTIC.	NOT NECESSARY	280.00	-
	LTA INSPECTION FOR OPC.		120.00	120.00
	TO CONDUCT FRONT LIGHTING TEST.	NOT NECESSARY	50.00	-
	TO CONDUCT FRONT PROTECTANT COATING.	NOT NECESSARY	500.00	-
	TO CONDUCT FRNT ANTI RUST COATING.	NOT NECESSARY	580.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING.	NOT NECESSARY	150.00	-
			5,771.00	1,100.00
GRAND TOTAL			7,466.60	1,620.20
RECOMMENDED COST OF REPAIRS				1,620.20

Report Ref No. CS/SMR21007412/Gvf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.