



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007412/Gvf3n2	
			Date: 07/03/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 711B	Veh. Inspected	SLR 6738D	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/07/21/2007	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	07/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER 2.0I	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1SJ5KC5JG097379	Colour	GREY	
Odometer	26826 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	TOURADOR	6 mm	
L/H Front Tyre	225/60 R17	TOURADOR	6 mm	
R/H Rear Tyre	225/60 R17	TOURADOR	6 mm	
L/H Rear Tyre	225/60 R17	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/07/2021	Inspection Date	30/08/2021	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 . SINGAPORE 319255			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	